

LICENSEE EVENT REPORT

*CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | G | A | E | I | H | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T 01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 6 | 7 | 1 | 1 | 0 | 5 | 8 | 1 | 8 | 1 | 2 | 0 | 1 | 8 | 1 | 9

02 | With the plant in startup and hot standby at 0 Mwt, while performing HNP-
03 | 2-3001, High Reactor Pressure Instrumentation Functional Test and Calibra-
04 | tion, 2B21-N023A, Reactor Pressure Switch, was found to actuate at 1063
05 | psig inc. Tech Specs Table 2.2.1-1 requires actuation at </-1045 psig
06 | +15.36 psig head correction. Redundant switches 2B21-N023B, C and D were
07 | operable. Plant operation or the health and safety of the public was
08 | not affected. This is repetitive as last reported on RO 50-366/1980-128.

09 | I | A | 11 | E | 12 | E | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16 | 17 | 8 | 1 | 1 | 10 | 8 | 0 | 3 | L | 0 | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 23 | N | 24 | N | 25 | B | 0 | 6 | 9 | 26

10 | The cause of this event has been attributed to setpoint drift. The switch,
11 | a Barksdale Model B2T, was immediately recalibrated per HNP-2-5279, Barks-
12 | dale Pressure Switch Calibration, and returned to service. No further
13 | reporting is required.

15 | C | 28 | 0 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Surveillance Testing | 32

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

18 | 0 | 0 | 0 | 40 | NA | 41

19 | Z | 42 | NA | 43

20 | N | 44 | NA | 45

8112090078 811201 PDR ADQCK 05000366 PDR S

NRC USE ONLY

NAME OF PREPARER R. T. Nix, Supt. of Maint.

PHONE 912-367-7781

LER No.: 50-366/1981-108
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-366

Narrative Report
for LER 50-366/1981-108.

With the plant in startup and hot standby at 0 MWt, while performing HNP-2-3001, High Reactor Pressure Instrumentation Functional Test and Calibration, 2B31-N023A, Reactor Pressure Switch RPS, was found to actuate at 1063 psig increasing. Tech Specs Table 2.2.1-1 requires actuation at less than or equal to 1045 psig +15.36 psig head correction. Redundant switches 2B21-N023B, C and D were operable. Plant operation or the health and safety of the public was not affected by this event. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-366/1980-128.

The cause of this event has been attributed to setpoint drift. The switch, a Barksdale Model B2T, was immediately recalibrated per HNP-2-5279, Barksdale Pressure Switch Calibration, and returned to service.

Unit I uses the same type of switches for this application. A generic review revealed no inherent problems however.