LICENSEE EVENT REPORT

*	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M I D C C 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
O 1	SOURCE L 6 0 5 0 0 0 3 1 6 7 1 0 2 9 8 1 8 1 3 0 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	DURING UNIT START-UP AND WHILE IN MODE 3, IT WAS DISCOVERED THAT THE TURBINE DRIVEN
0 3	LAUXILIARY FEED PUMP (TDAFP) WAS APPROXIMATELY 150°F WHILE IN STANDBY CONDITION. THE
0 4	LAUX. FEEDWATER LINES TO THE STEAM GENERATORS FROM THE TDAFP WERE CLOSED AND THE PUMP
0 5	IALLOWED TO COOL. THE TWO MOTOR DRIVEN AUX, FEED PUMPS REMAINED OPERABLE DURING THIS
0 6	LTIME. WHEN THE TDAFP WAS COOLED, IT WAS TESTED AND THE STEAM GENERATORS FED SATIS-
0 7	LFACTORILY. THERE WAS NO ADVERSE EFFECT ON THE HEALTH AND SAFETY OF THE PUBLIC.
0 B	SIMILAR EVENTS: 50-316/81-032.
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
10	LER/RO EVENT YEAR REPORT NO. CODE TYPE NO.
11	WERE CLOSED SO THE TDAFP COULD COOL DOWN. WHEN THE AUX. FEEDWATER PUMP COOLED, IT WAS
1 2	IMPOSSIBLE TO DETERMINE WHICH CHECK VALVE WAS LEAKING BACK AND THE CONDITION DID NOT
1 3	L REOCCUR. CAUTION TAGS HAVE NOW BEEN PLACED ON THE 4 STEAM GENERATOR AUX. FEEDWATER
7 8	VALVES, WARNING THE OPERATOR NOT TO CLOSE THEM UNTIL IT WAS DETERMINED WHICH CHECK continued 80 FACILITY STATUS SPOWER OTHER STATUS OPERATOR OBSERVATION LA (31) OPERATOR OBSERVATION
	9 10 12 13 44 45 46 80
1 6	PELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA N
1 7	NUMBER OF TYPE DESCRIPTION (39) NA NA NA
D B	PERSONNEL INJURIES NUMBER DESCRIPTION 41
3 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 43
1 9	NA 8112100391 811130 -80
20	PDR ADOCK 05000316 NRC USE ONLY STORY NA PDR ADOCK 05000316 NRC USE ONLY S PDR 68 69 80 5
	NAME OF PREPARER C. E. MURPHY PHONE: (616) 465-5901 ext. 1305 %

ATTACHMENT TO LER 81-063/03L-0

10) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS
VALVE WAS LEAKING.