

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I | A | D | A | C | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CON-T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 10 | 10 | 0 | 3 | 3 | 1 | 7 | 1 | 1 | 1 | 8 | 8 | 1 | 3 | 1 | 2 | 0 | 2 | 8 | 1 | 9
7 8 9 DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, ops personnel attempted to cycle Rx Water Cleanu
0 3 | p System (RWCU) return isolation valve MOV-2740. No flow change occurred
0 4 | during vlv. cycling. Valve indicated closed with a 70 gpm flow thru the R
0 5 | WCUs. The valves isolation function was therefore compromised. Tech Spec
0 6 | 3.7.D lists the operability reqmts. for this valve. The RWCUs was isola
0 7 | ted pending valve repair. MOV-2740 was returned to service within 3 hours
0 8 | . One similar non-reportable event in which MOV-2740 would not open.

0 9 | SYSTEM CODE | C | G | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | V | A | L | V | E | X | 14 | COMP SUBCODE | F | 15 | VALVE SUBCODE | D | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 | LER/RO REPORT NUMBER | 8 | 1 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 4 | 0 | 24 | 26 | OCCURRENCE CODE | 0 | 1 | 28 | 29 | REPORT TYPE | T | 30 | REVISION NO. | 0 | 32
ACTION TAKEN | B | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NPRO-4 FORM SUB. | N | 24 | PRIME COMP SUPPLIER | A | 25 | COMPONENT MANUFACTURER | A | 3 | 1 | 9 | 5 | 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The valve stem clamp setscrew became loose and the clamp key dropped out
1 1 | . The stem then rotated when the motor operator was cycled without moving
1 2 | the vlv. disc. The key was reinstalled and the stem clamp restored to ori
1 3 | ginal config. MOV-2740 limit switches reset. The vlv. was cycled-found sa
1 4 | t, MOV-2740 is a 4 in. Anchor globe vlv. Design Review to be initiated.

1 5 | FACILITY STATUS | E | 28 | % POWER | 0 | 6 | 6 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43 | 8112100404 811202 PDR ADOCK 05000331 S PDR
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45 | NRC USE ONLY
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

DUANE ARNOLD ENERGY CENTER

Iowa Electric Light and Power Company

Licensee Event Report - Supplemental Data

Docket No. 050-0331

Licensee Event Report Date: 81-040

Reportable Occurrence No: 12-2-81

Event Description

During normal power operation, operations personnel attempted to cycle reactor water cleanup (RWCU) system return isolation valve MOV-2740. It was found that no flow changes occurred in response to the valve being cycled. The valve indicated closed with a flow of 70 gpm thru the RWCU system. This condition resulted in the isolation function of the valve being compromised. Technical Specification 3.7.D lists the operability requirements for this valve. The RWCU System was isolated and MOV 2740 closed manually pending repairs to the valve. MOV 2740 was repaired and returned to service within 3 hours. There has been one similar but non-reportable occurrence in which MOV-2740 would not open.

Cause Description

An investigation revealed that the valve stem clamp setscrew had become loose, allowing the clamp key to drop out. The stem was then able to freely rotate whenever the motor operator was cycled resulting in no valve disc movement.

Corrective Action

The key was reinstalled and the stem clamp restored to its original configuration. The limit switches of MOV-2740 were reset. The valve was cycled and found to be operating properly. MOV-2740 is a 4 inch Anchor globe valve. A Design Review will be initiated. As an interim measure the number of valves of similar design in the plant will be identified and a representative sample of valves will be inspected to determine if a potential generic problem exists. Additional near term corrective action will be initiated if this sampling program identifies similar problems in other valves.