

The Light company

Houston Lighting & Power P.O. Box 1700 Houston, Texas 77001 (713) 228-9211

December 4, 1981
ST-HL-AE-763
SFN: V-0530

Mr. John T. Collins
Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Dr., Suite 1000
Arlington, TX 76012



Dear Mr. Collins:

South Texas Project
Units 1 & 2
Docket Nos. STN 50-498, STN 50-499
Final Report Concerning
Westinghouse EMD Gate Valves

On July 2, 1981, pursuant to 10CFR50.55(e), Houston Lighting & Power Company notified your office of an item concerning closure problems with Westinghouse (W) Electro-Mechanical Division (EMD) manufactured gate valves. Our final report regarding this item is attached.

If you should have any questions concerning this item, please contact Mr. Michael E. Powell at (713) 676-2592.

Very truly yours,

A. W. Oprea, Jr.
Executive Vice President

MEP/blt
Attachment

8112110251 811204
PDR ADDCK 05000498
S PDR

IE 27
S/11

Houston Lighting & Power Company

cc: G. W. Oprea, Jr.

J. H. Goldberg

J. G. Dewease

D. G. Barker

C. G. Robertson

H. Pyle, III

R. A. Frazar

D. R. Beeth

J. W. Williams

J. W. Briskin

J. E. Geiger

D. E. Sells

(NRC)

H. S. Phillips

(NRC)

J. O. Read

(Read-Poland, Inc.)

M. D. Schwarz

(Baker & Botts)

R. Gordon Gooch

(Baker & Botts)

J. R. Newman

(Lowenstein, Newman, Reis, & Axelrad)

STP RMS

Director, Office of Inspection & Enforcement

Nuclear Regulatory Commission

Washington, D. C. 20555

December 4, 1981

ST-HL-AE-763

SFN: V-0530

Page 2

R. L. Range/G. W. Muench
Central Power & Light Company
P. O. Box 2121
Corpus Christi, Texas 78403

Charles Bechhoefer, Esquire
Chairman, Atomic Safety & Licensing Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Hancock/G. Pokorny
City of Austin
P. O. Box 1088
Austin, Texas 78767

Dr. James C. Lamb, III
313 Woodhaven Road
Chapel Hill, North Carolina 27514

J. B. Poston/A. vonRosenberg
City Public Service Board
P. O. Box 1771
San Antonio, Texas 78296

Mr. Ernest E. Hill
Lawrence Livermore Laboratory
University of California
P. O. Box 808, L-46
Livermore, California 94550

Brian E. Berwick, Esquire
Assistant Attorney General
for the State of Texas
P. O. Box 12548
Capitol Station
Austin, Texas 78711

William S. Jordan, III
Harmon & Weiss
1725 I Street, N. W.
Suite 506
Washington, D. C. 20006

Lanny Sinkin
Citizens Concerned About Nuclear Power
5106 Casa Oro
San Antonio, Texas 78233

Citizens for Equitable Utilities, Inc.
c/o Ms. Peggy Buchorn
Route 1, Box 1684
Brazoria, Texas 77422

Jay Gutierrez, Esquire
Hearing Attorney
Office of the Executive Legal Director
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Revision Date 10-29-81

Final Report Concerning
Westinghouse EMD Gate Valves
December 4, 1981

I. Description of the Incident

On July 2, 1981, pursuant to 10CFR50.55(e), Houston Lighting & Power Company (HL&P), notified your office of an item concerning closure problems with Westinghouse (W) Electro-Mechanical Division (EMD) manufactured gate valves. W had identified to HL&P that several three (3) and four (4) inch gate type valves had been shown by tests and/or analyses by W to have a potential for not closing against differential pressure.

Subsequent to HL&P's July 2, 1981 notification, HL&P received NRC Inspection & Enforcement (I&E) Bulletin 81-02, Supplement #1, "Failure of Gate Type Valves to Close Against Differential Pressure", which identified that W had performed analyses which predicted that closure problems could be anticipated with 6, 8, 10, 12, 14, 16 and 18-inch gate valves in addition to the 3 and 4-inch gate valves.

An evaluation program is being conducted by W and includes flow tests and analyses. Based upon the results to date, W has determined that modifications will be necessary to valves supplied to the South Texas Project (STP) in order to assure that the functional requirements are met. However, failure of the valves to meet these requirements does not create a substantial safety hazard.

II. Corrective Action

Depending on the system closing differential pressure requirements and the valve model in question, the modification to guarantee full closure can vary. The modification could involve any combination of the following items:

- (1) Torque switch adjustment;
- (2) Increasing the operator gear ratio to guarantee adequate thrust capacity at eighty percent (80%) voltage;
- (3) Rewiring the operator for limit closing control;
- (4) Changing the operator torque switch spring pack;
- (5) Changing to a larger foot-pound rated motor; or
- (6) Changing to a larger size Limitorque operator.

The modifications of the subject valves will be made in accordance with the W procedure for administering field changes. A Field Change Notice (FCN) will be issued by W which will provide the scope of the corrective action to be taken. Based on the current W schedule, the FCN for both South Texas Project (STP) Units will be issued by the end of March, 1982, with modifications/repairs to be completed by December, 1982.

III. Recurrence Control

A recurrence control program is not considered necessary because the situation appears to be unique to W EMD gate valves.

IV. Safety Analysis

An evaluation of the safety consequences of the valves failing to close was performed in response to NRC I&E Bulletin 81-02, Supplement #1. Based on the evaluation, failure of these valves to close would have no significant safety consequences. The attached table from our response to the subject Bulletin lists the subject W gate valves intended for use in safety-related systems, their planned service, the differential pressure against which they will be required to close, and the safety consequences of the valves failing to close.

ATTACHMENT

W-EMD VALVE ID	PLANNED SERVICE APPLICATION	HL&P VALVE # (W)	MAXIMUM ΔP (psi)	FAILURE ANALYSIS
3GM88FNB	Pressurizer PORV Block Valve	XRC 001 A, B (1-8000 A,B)	2500	The present design does not require the block valves to close under full flow conditions. These valves are used to isolate PORV's if they are leaking. The failure of one of these valves to close under full flow conditions would be the same as a Failed Open PORV (assuming PORV is already opened and fails to close). The consequences of this failure are covered by present accident analysis in the FSAR.
6GM72FBA	Volume Control Tank Discharge Isolation	XCV 112 B (LCV-112 B) XCV 113 A (LCV-113A)	100	These valves in series are located on the VCT Discharge line that provides suction to the CVCS charging pumps. These valves are closed upon opening of the valves that permit CVCS charging pump suction from the RWST and when either SI signal or VCT lo-lo level signal is present. Failure of one valve to close completely may reduce the differential pressure across the second valve sufficient to permit its closure. Failure of these valves to close would have no significant safety consequences.
6GM72FBA	CVCS Charging Pump Suction to RWST	XCV 112 C (LCV-112C) XCV 113 B (LCV-113B)	200	These valves are in parallel flow paths from the RWST to the CVCS charging pump suction header. These valves are normally closed and are used only in abnormal situations when the charging pumps are used to provide water from the RWST to the Reactor Coolant System. These valves are interlocked to prevent closure when an SI signal or VCT lo-lo level signal is present. Failure of these valves to close would have no significant safety consequences.
4GM88FND	CVCS Letdown Upstream of Regenerative Heat Exchanger	LCV 465 LCV 468	2500	These two valves in series provide isolation of the CVCS letdown from the RCS. These valves would be automatically closed on Pressurizer low level that might be caused by a break in the safety class 2 pipe of the regenerative heat exchanger downstream of the valves. The two valves in series provide redundancy. Failure of one valve to close completely may reduce the differential pressure across the second valve sufficiently to permit closure. If the blowdown is not

W-EMD VALVE ID	PLANNED SERVICE APPLICATION	HL&P VALVE # (W)	MAXIMUM DP (psi)	FAILURE ANALYSIS
4GM74FEB	CVCS Letdown Containment Iso- lation Valves	XCV023 (8133) XCV024 (8134)	700	<p>terminated, the consequences are covered by present accident analyses in the FSAR. Failure of the valves to close completely has no unreviewed safety consequences.</p> <p>These valves provide a Containment Isolation function. High differential pressure would occur on a Containment Isolation Signal. For a pipe break inside Containment, the differential pressure across the valves would be reduced immediately, permitting the valves to close.</p> <p>For failure of the two upstream isolation valves (Westinghouse EMD valves) in conjunction with a letdown pipe break outside Containment, there are motor-operated packless metal diaphragm valves used as Letdown Orifice isolation valves that could be manually operated to terminate flow. When the flow is reduced, the valves LCV 465, LCV 468, XCV 023 (8133) and XCV 024 (8134) would then be able to close. Also, partial closure of one valve may reduce the differential across the second valve sufficiently to permit the second valve to close. Failure of XCV 023 (8133) and XCV 024 (8134) to close would have no significant safety consequences.</p>
4GM78FPA	CVCS Charging Line Isolation	XCV 025 (8135)	3100	<p>The failure of this valve for a pipe break inside or outside Containment reduces the redundancy for Containment Isolation. For outside Containment, there are 3 check valves downstream that would prevent blowdown of the RCS. For inside Containment, the Charging Pumps can be stopped and the differential pressure across the valve would be reduced immediately, permitting the valve to close.</p>
4GM72FBA	Charging Pump Suction Valve from Boric Acid Transfer Pump	XCV 218 (8358)	0	<p>This valve is normally closed and provides a means to have CVCS Charging Pumps take suction from 4 weight percent boric acid solution. The valve is in series with a check valve; failure to close would permit flow from boric acid transfer pumps to the suction of the charging pumps. Flow may be stopped by turning off the BAT pumps. Backflow into BRS is precluded by check valve. The failure of this valve to close has no significant safety consequences.</p>

W-EMD VALVE ID	PLANNED SERVICE		MAXIMUM ΔP (psi)	FAILURE ANALYSIS
	APPLICATION	HL&P VALVE # (W)		
16GM72FBA	Safety Injection Suction Valve from RWST	XSI 001 A, B, C (8801 A,B,C)	200	Valve is closed for recirculation phase following a LOCA. Failure of the valve to close would result in a loss of redundancy for preventing backflow to the RWST. Failure of the valve to close has no significant safety consequences.
6GM77FHA	High Head Safety Injection Pump Discharge Isolation Valve/ Containment Isolation	XSI 004 A, B, C (8804 A,B,C)	100	This valve provides pump isolation and also serves as the Containment Isolation Valve. The valve is normally open. Failure of the valve to close against backflow from the RCS has no significant safety consequences because there are 2 check valves which could prevent blowdown of the RCS.
6GM78FNB	HHSI to Accumulator Isolation Valve	XSI 006 A, B, C (8806 A,B,C)	0	This valve closes for switchover from Cold Leg injection to Hot Leg injection. Failure of valve to close during recirculation will degrade flow to Hot Legs. Pressure differential across valve can be reduced to permit closure by momentarily interrupting SI (by stopping pump or manual action). Failure of the valve to close reduces the redundancy for Hot Leg recirculation.
6GM78FNB	HHSI to Hot Leg Injection Iso- lation Valve	XSI 008 A, B, C (8808 A,B,C)	0	This valve is opened to provide SI switchover from Cold Leg injection to Hot Leg injection. If switchover back to Cold Leg is required, failure of the valve to close would degrade Cold Leg injection flow. However, SI could be momentarily interrupted to reduce differential pressure across valve permitting it to close.
16GM72FBD	Emergency Sump Recirculation Isolation Valve	XSI 016 A, B, C (8816 A,B,C)	100	This valve must open to permit SI recirculation. The valve is required for isolating a passive failure between the sump valve and the next motor-operated valve. High differential pressure should not be present when the valve is required to close.
8GM74FEA	Low Head Safety Injection Pump Discharge Isolation Valve/Con- tainment Isolation Valve	XSI 018, A, B, C (8818 A,B,C)	100	This valve serves as a pump isolation valve and as a Containment Isolation Valve. The valve is normally open. Reverse flow in the line is stopped by the inside Containment check valve. Failure of the valve to close reduces Containment Isolation redundancy.

W-EMD VALVE ID	PLANNED SERVICE		MAXIMUM ΔP (psi)	FAILURE ANALYSIS
	APPLICATION	HL&P VALVE # (W)		
BGM78FNB	LHSI to Hot Leg Injection Isolation valve	XRH 019 A, B, C (8819 A,B,C)	200	Same as for XSI 008 (8808)
BGM78FNB	LHSI to Accumulator Isolation Valve	XRH 031 A, B, C (8901 A,B,C)	200	Same as for XSI 006 (8806)
12GM78FND	Accumulator Tank Discharge Isolation	XSI 039 A, B, C (8949 A,B,C)	0	This valve is normally open during power operation and is closed only when required to prevent blowdown as RCS is depressurized in a normal shutdown. The accumulator may also be depressurized by venting the N ₂ to the Containment. The failure of the valve to close under high differential pressure has no significant safety consequences.
12GM88SEB	RHR Suction Isolation Valves from RCS	XRH 060 A, B, C (9000 A,B,C) XRH 061 A, B, C (9001 A,B,C)	700	These valves are normally closed valves and can only be opened when RCS pressure is less than approximately 425 psig. When the valves are open, they automatically close when RCS pressure is approximately 750 psig. If valves fail to close under high differential pressure, the operator can take steps to reduce RCS pressure until the valves are able to close. Also, with two valves in series, partial closure of the first valve may reduce differential pressure across the second valve permitting its closure. Failure of these valves to close would reduce redundancy.
BGM74FCA	CSS Pump Discharge Isolation Valve/Containment Isolation Valve	XCS 001 A, B, C (9100 A,B,C)	200	These valves are normally closed. They open to provide Containment spray and are used for Containment Isolation after Containment spray has been terminated. A check valve (IRC) would provide isolation capability. Failure of these valves to close reduces Containment isolation redundancy.