



LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81067 Technical Specification Involved Table 3.2.E

Reported Under Technical Specification 6.7.2.b(1) \*Date due NRC: 12/6/81

Date of Occurrence 11/6/81 Time of Occurrence 0700 Unit 1

Identification and Description of Occurrence:

High alarm on the drywell air sampler was set above 3X background.

Conditions Prior to Occurrence:

Unit 1 at 100%.

Unit 2 at 100%.

Unit 3 in refueling outage.

Action specified in the Technical Specification Surveillance Requirements met  
due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Setpoints were not revised down following decrease in background.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Setpoints on the NMC model AM-331F(BF) continuous air monitor were reset to 3X background, SI was revised, and a program was established to routinely determine setpoint values.

Failure Data:

None

\*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: SLY