

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

0	1
7	8

REPORT SOURCE

1	6	0	5	0	0	0	2	6	0	7	1	1	0	6	8	1	8	1	2	0	4	8	1	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7 8 9 10 11 12 13 14 15 16

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 S C 11 D 12 Z 13 I N S T R U 14 E 15 Z 16

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2/

4 9 10
PRIORITY
10
8 9 10
ISSUED DESCRIPTION (15)
2 3 4 5 6 7 8 9 10
N (14)
8112140197 811204
PDR ADOCK 05000260
S PDR
NRC USE ONLY

PHONE: (205) 729-6134

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81061 Technical Specification Involved Table 3.2.E

Reported Under Technical Specification 6.7.2.b(1)* Date due NRC: 12/6/81

Date of Occurrence 11/6/81 Time of Occurrence 0700 Unit 2

Identification and Description of Occurrence:

High alarm on the drywell air sampler was set above 3X background.

Conditions Prior to Occurrence:

Unit 1 at 100%.

Unit 2 at 100%.

Unit 3 in refueling outage.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Setpoints were not revised down following decrease in background.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Setpoints on the NMC model AM-331F(BF) continuous air monitor were reset to 3X background, SI was revised, and a program was established to routinely determine setpoint values.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: 1/1