

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 1 1 1 1 1 1 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 0 1	N	C	M	G	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5	
7 8	9	LICENSEE CODE	14	15														25	26	LICENSE NUMBER	27	28	LICENSE TYPE	29	30	57 CAT 54

CONT

7 0 1	REPORT SOURCE	L	5	0	5	0	0	0	3	6	9	7	1	0	2	8	8	1	8	1	1	3	0	8	1	9
7 8	9	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

- 0 2 While at 30% power, investigation of an annunciator alarm discovered that 2
- 0 3 UHI accumulator discharge isolation valves were not fully open. The UHI accu-
- 0 4 mulator was subsequently declared inoperable per T.S.3.5.1.2 which is reporta-
- 0 5 ble pursuant to T.S.6.9.1.13(b). Since the degraded configuration of the plant
- 0 6 was temporary (approximately 1 minute), and the capability to correct the situ-
- 0 7 ation was available (by opening the affected valves), the health and safety of
- 0 8 the public were not affected.

7 0 9	SYSTEM CODE	S	F	11	CAUSE CODE	E	12	CAUSE SUBCODE	X	13	COMPONENT CODE	P	I	P	E	X	X	14	COMP. SUBCODE	A	15	VALVE SUBCODE	Z	16			
7 8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33		
17	REPORT NUMBER	8	1	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	
18	LER/RO REPORT NUMBER	8	1	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	
19	ACTION/TAKEN ACTION	E	Z	18	19	20	Z	21	Z	22	Z	23	Z	24	Z	25	Z	26	Z	27	Z	28	Z	29	Z	30	Z
20	EFFECT ON PLANT	Z	Z	20	Z	21	Z	22	Z	23	Z	24	Z	25	Z	26	Z	27	Z	28	Z	29	Z	30	Z	31	Z
21	SHUTDOWN METHOD	Z	Z	20	Z	21	Z	22	Z	23	Z	24	Z	25	Z	26	Z	27	Z	28	Z	29	Z	30	Z	31	Z
22	HOURS	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
23	ATTACHMENT SUBMITTED	Y	23	24	25	26	27	28	29	20	21	22	23	24	25	26	27	28	29	20	21	22	23	24	25	26	
24	NPPD-4 FORM SUB.	N	24	25	26	27	28	29	20	21	22	23	24	25	26	27	28	29	20	21	22	23	24	25	26	27	
25	PRIME COMP. SUPPLIER	L	25	26	27	28	29	20	21	22	23	24	25	26	27	28	29	20	21	22	23	24	25	26	27	28	
26	COMPONENT MANUFACTURER	P	0	7	0	26	27	28	29	20	21	22	23	24	25	26	27	28	29	20	21	22	23	24	25	26	27

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑦

- 1 0 The fitting (1/2" Parker-Hannifin) from the low leg impulse line to the level
- 1 1 switch was loose, resulting in a leak which caused the level switch to give a
- 1 2 signal to close. The valves were opened and the leaking fitting checked for
- 1 3 proper installation and tightened.

7 1 4	FACILITY STATUS	B	28	% POWER	0	3	0	29	N/A	44	OTHER STATUS	30	45	46	METHOD OF DISCOVERY	31	DISCOVERY DESCRIPTION	32						
7 8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

7 1 5	ACTIVITY CONTENT	Z	33	Z	34	N/A	35	AMOUNT OF ACTIVITY	36	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59
7 8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

7 1 6	RELEASED OR RELEASE	Z	33	Z	34	N/A	35	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61
7 8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

7 1 7	PERSONNEL EXPOSURES	0	0	0	37	Z	38	DESCRIPTION	39	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59
7 8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

7 1 8	PERSONNEL INJURIES	0	0	0	40	41	42	DESCRIPTION	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59
7 8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

7 1 9	LOSS OF OR DAMAGE TO FACILITY	Z	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64
7 8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

7 2 0	PUBLICITY	N	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66
7 8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

NRC USE ONLY

NAME OR PREPARED Phillip B. Nardoci
8112140205 811130
PDR ADOCK 05000369
S PDR

PHONE 704-373-7432