

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	--	---

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 5

CON'T

0	1	R	L	6	0	5	0	0	0	2	7	2	7	1	1	2	9	8	1	8	1	2	0	9	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On November 28, 1981, during a routine containment inspection, an operator discovered service water leaking from the fourth from bottom primary cooling coil, on No. 12 Containment Fan Coil Unit (CFCU), at a rate of approximately 0.8 gallons per minute. The CFCU was isolated by closing the inlet and outlet valves from the control room, but remained operable and capable of functioning adequately under emergency conditions. No. 12 CFCU was declared inoperable and Action Statement 3.6.2.3.a was entered at 1119 hours, November 29, 1981.

0	9	S	B	11	E	12	B	13	H	T	E	X	C	H	14	G	15	Z	16	8	1	1	0	9	0	1	T	0	B	A	19	Z	20	Z	21	0	0	0	0	22	Y	23	Y	24	N	25	W	1	2	0	26
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	---	---	---	---	---	----	---	----	---	----	---	---	---	---	----	---	----	---	----	---	----	---	---	---	---	----

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO. ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The leakage was due to primary coil failure. The leaking cooling coil was satisfactorily repaired with Belzona metal filler and the CFCU was tested satisfactory and returned to service. Action Statement 3.6.2.3.a was terminated at 1120 hours, December 1, 1981. (81-92, 81-94, 81-96, 81-105, 81-108)

1	5	E	28	0	6	9	29	N/A	30	B	31	Leak discovered during routine inspection.	32	Z	33	Z	34	N/A	35	N/A	36	0	0	0	37	Z	38	N/A	39	0	0	0	40	N/A	41	Z	42	N/A	43	N	44	N/A	45	8112210323	811209	PDR	ADOCK	05000272	PDR	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	----	---	---	---	----	-----	----	---	----	--	----	---	----	---	----	-----	----	-----	----	---	---	---	----	---	----	-----	----	---	---	---	----	-----	----	---	----	-----	----	---	----	-----	----	------------	--------	-----	-------	----------	-----	----	----	----	----	----	----	----	----	----	----	----	----	----

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION ACTIVITY RELEASED CONTENT OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION PERSONNEL INJURIES NUMBER DESCRIPTION LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION PUBLICATION ISSUED DESCRIPTION

NAME OF PREPARER Frank Dickey

PHONE: 609-935-0998