TELECOPY TO NRC

DEC 22 1981

U.S. Nuclear Regulatory Commission Region II 101 Marietta Street, WW Suite 3100 Arlanta, Georgia 30303 REGIONAL DIRECTOR DEPUTY DIRECTOR ASSISTANT TO DIRECTOR DIRECTOR, RRPI DIRECTOR, EPOS DIRECTOR, ENF/INV DIRECTOR, ETI PUBLIC AFFAIRS OFFICER

SQR0-50-328/81152

Reported Under Technical Specification: 6.9.1.12.b

Date of Occurrence: 12/22/81 Time of Occurrence: 0300 CST

Technical Specification Involved: 3.1.1.3

Conditions Prior to Occurrence

Unit 2 in mode 2, 0% power, RCS temperature and pressure 547 degrees V and 2235 paig.

Identification and Description of Occurrence

While increasing reactor parameters for power ascension, control rod withdrawal limits established in accordance with the action statement associated with limiting condition for operation 3.1.1.3 of the Sequoyab Technical Specifications were violated. These operating limits were established as required by LCO 3.1.1.3 in Special Report 31-3 sent to Mr. James P. O'Reilly on November 13, 1981.

Apparent Cause of Occurrence

The operating limits established were not in startup procedures, and the time period since November 13, 1981, contributed to the inadvertent omission of referencing the operating limits to maintain a negative moderator temperature coefficient during Voit 2 startup.

Other Related Events

Reference the memorandum and enclosed Special Report from H. J. Green to Mr. James P. O'Reilly dated November 13, 1981.

Corrective Action Taken or Planned

The operator diluted the boron concentration in order to reestablish applicable control rod positions to within established operating limits within an hour. A temporary change is being proposed to our Technical Instruction 21 (Calculation of Estimated Critical Conditions) with a note to caution the unit operators on established control rod withdrawal limits.

Ret A

C. C. Mason Power Plant Superintendent

Securvah Noclear Plant 8112290323 811222 PDR ADOCK 05000328 S PDR

1693