

Public Service Company Of Colorado

16805 Road 19 1/2, Platteville, Colorado 80651-9298

December 17, 1981 Fort St. Vrain Unit No. 1 P-81318

Mr. John T. Collins, Regional Administrator Region IV Nuclear Regulatory Commission 611 Ryan Plaza Drive Suite 1000 Arlington, Texas 76011 PECEIVES DEC 2 8 1981

Reference: Facility Operating License No. DPR-34

Docket No. 50-267

Dear Mr. Collins:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/81-072, Preliminary, submitted per the requirements of Technical Specification AC 7.5.2(b)1.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurronce Report No. 50-267/81-072.

Very truly yours,

Don Warenbourg by FSBorst

Don Warembourg Manager, Nuclear Production

DW/cls Enclosure cc: Director, MIPC

8112290534 811217 PDR ADOCK 05000267 PDR

E22

OCCURRENCE REPORT DISTRIBUTION

| | Number of Copies | | |
|--|------------------|----|---|
| Department of Energy | | 1 | (P Letter) |
| Department of Energy | | 1 | (P Letter) |
| Department of Energy | | 1 | (P Letter) (Original of P Letter |
| Region IV Office of Inspection and Enforcement Nuclear Regulatory Commission 611 Ryan Plaza Drive Suite 1000 Arlington, Texas - 76012 76011 | | V | and Copy of LER) |
| Director | | 1 | (P Letter, LER) |
| <pre>Mr. Richard Phelps FSV, GA, Site Representative General Atomic Company P. 0. Box 426 Platteville, Colorado 80651</pre> | •••• | 10 | (Original of FPLG Letter plus Two Copies, One Copy of P Letter, One Copy of LER) |
| Mr. Bill Lavalee | | 1 | (P Letter, LER) |
| NRC Resident Site Inspector | | 1 | (P Letter, LER) |

| REPORT | DATE: | December | 17, | 1981 |
|---------|------------|----------|-----|------|
| OCCURRE | ENCE DATE: | November | 17. | 1981 |

REPORTABLE OCCURRENCE 81-072 ISSUE 0 Page 1 of 4

FORT ST. VRAIN NUCLEAR GENERATING STATION PUBLIC SERVICE COMPANY OF COLORADO 16805 WELD COUNTY ROAD 19 1/2 PLATTEVILLE, COLORADO 80651-9298

REPORT NO. 50-267/81-072/03-L-0

Preliminary

IDENTIFICATION OF OCCURRENCE:

During a routine surveillance check performance on November 17, 1981, the setpoint of the PCRV rupture disk assembly M-11701 was found to be 847 psig. Since this setpoint is higher than the 832 psig ± 1% allowable by Fort St. Vrain Technical Specification LSSS 3.3, Table 3.3.1.2(c), it is being reported per Fort St. Vrain Technical Specification AC 7.5.2(b)1.

EVENT DESCRIPTION:

With the reactor shutdown and depressurized for scheduled maintenance, the high set rupture disk M-11701 was removed from service for a scheduled surveillance calibration bench test. The "as found" pressure setpoint was 847 psig. The acceptance criterion of LSSS 3.3, Table 3.3.1.2(c) requires the set pressure co be 832 psig + 1% (824 psig to 840 psig).

Refer to Figure 1. Before the test gas pressure is applied, the cutter, ①, is removed, and a special ring is installed to limit the travel of the Belleville washers ②. The washers snap-over when the set pressure is reached. Adjustment of the set pressure is made by positioning of the threaded ring ③. When the set pressure is reached, the diaphragm and washers travel a few thousandths of an inch, which produces an audible "thump." The plant instrumentation personnel know from previous experience that the setpoint of the Belleville washers decreases slightly with subsequent snap-overs during testing. Therefore, the snap-over test was conducted two additional times with snap-overs occurring at 831 psig and 831 psig, respectively. The last two tests were within the specified acceptable range. The average of the three tests was 836 psig, which is satisfactory, so no further adjustments were required. The remainder of the surveillance was completed, and the rupture disk assembly was returned to service.

During this surveillance interval, the low set rupture disk, M-11702, was operable and provided the required overpressure protection. M-11702 was last calibrated in 1980, and was left within the specified setpoint range.

REPORTABLE OCCURRENCE 81-072 ISSUE 0 Page 2 of 4

CAUSE DESCRIPTION:

The rupture disk movement setpoint being out of tolerance was caused by drift of the Belleville washer operating point over the period since its' last calibration surveillance.

CORRECTIVE ACTION:

The snap-over test was conducted three times with the last two of the tests within the required setpoint band. The remainder of the surveillance was completed, and the rupture disk assembly was returned to service.

An evaluation of the rupture disks is being conducted by the Public Service Company of Colorado's Nuclear Engineering Division. The results of this evaluation will be included in a future supplemental report.

REPORTABLE OCCURRENCE 81-072 ISSUE 0 Page 3 of 4



FIGURE 1

erces

REPORTABLE OCCURRENCE 81-072 ISSUE 0 Page 4 of 4

Prepared By: CoBeer A. Dickerson Robert A. Dickerson Technical Services Technician

Reviewed By:

Charler Fuller Charles

Technical Services Engineering Supervisor

Reviewed By: 2 Verley Martin Block Edwin D. Hill

Station Manager

Approved By: Don Warembourg by FJBorst Don Warembourg

Manager, Nuclear Production