

LICENSEE EVENT REPORT

CONTROL BLOCK:

| | | | | | | |
|--|--|--|--|--|--|--|
| | | | | | | |
|--|--|--|--|--|--|--|

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---------------|---|---|---|---|----|---|---|---|---|----------------|---|---|---|---|----|---|---|---|---|----|---|--|--|---|--------------|--|--|--|--|----|--|--|--|--|-----|--|----|--|---|--|
| 0 | 1 | 0 | H | D | B | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5 | | | | | | | | | | | | | | | | |
| 1 | | 8 | | 9 | | | | | 14 | | | | | 15 | | | | | 25 | | | | | 26 | | | | | 30 | | | | | 57 | | | | | CAT | | 58 | | 5 | |
| | | | | LICENSEE CODE | | | | | | | | | | LICENSE NUMBER | | | | | | | | | | | | | | | LICENSE TYPE | | | | | | | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---------------|---|----|---|----|---|---|---------------|---|----|---|---|------------|---|----|---|---|---|---|----|---|---|-------------|--|----|--|--|--|--|
| 0 | 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 4 | 6 | 7 | 1 | 1 | 0 | 4 | 7 | 8 | 8 | 1 | 2 | 1 | 5 | 8 | 1 | 9 | | | | | | |
| 1 | | 8 | | 60 | | 61 | | 66 | | | | | 69 | | | | | 74 | | | | | 75 | | | | | 80 | | | | |
| | | | | REPORT SOURCE | | | | | | | DOCKET NUMBER | | | | | EVENT DATE | | | | | | | | | | REPORT DATE | | | | | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 (NP-33-78-127) During performance of surveillance testing on November 4, 1978, it was noticed that containment post-accident radiation monitor RE 5029 had a low flow alarm.

03 RE 5029 was declared inoperable at 1745 hours on November 4, 1978. This report is being submitted as documentation of a component failure. There was no danger to the health and safety of the public or station personnel. The other containment post-accident radiation monitor, RE 5030, was operable during the period that RE 5029 was inoperable.

| | | | | | | | | | | | | | |
|---------------------------|--|-----------------------------------|--|-----------------------------|--|------------------------------------|--|----------------------------|--|--------------------------------|--|--|--|
| SYSTEM CODE B B (11) | | CAUSE CODE E (12) | | CAUSE SUBCODE B (13) | | COMPONENT CODE M O T O R X (14) | | | | COMP. SUBCODE Z (15) | | VALVE SUBCODE Z (16) | |
| EVENT YEAR 7 8 (17) | | SEQUENTIAL REPORT NO. 1 1 (18) | | OCCURRENCE CODE 0 3 (19) | | REPORT TYPE X (20) | | REVISION NO. 2 (21) | | ACTION TAKEN A (22) | | FUTURE ACTION F (23) | |
| EFFECT ON PLANT Z (24) | | SHUTDOWN METHOD Z (25) | | HOURS 0 0 0 0 (26) | | ATTACHMENT SUBMITTED Y (27) | | NPRD-4 FORM SUB. Y (28) | | PRIME COMP. SUPPLIER A (29) | | COMPONENT MANUFACTURER R 1 6 5 (30) | |

CAUSE DESCRIPTOR AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 The cause of the occurrence is due to component failure of both the pump motor and de-

1 1 tector assembly. These motors have been drawing excessive current and have failed in

1 2 the past. The motor and pump were replaced and RE 5029 was declared operable on

1 3 11/24/78. FCR 78-521, which reduces the speed of the pump in RE 5029, has been

1 4 implemented.

8 9
FACILITY STATUS (26) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)
1 5 B 0 0 0 NA Surveillance Test ST 5099.05
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1 6 Z Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
PERSONNEL EXPOSURES
NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
PERSONNEL INJURIES
NUMBER DESCRIPTION (41)
1 8 0 0 0 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)
1 9 Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 N NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
8112310352 811215
PDR ADDCK 05000346
S PDR
NRC USE ONLY

DVR 78-163

NAME OF PREPARER

Lynn Schwennig

PHONE

(419) 259-5000, Ext. 251

622