

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | C | M | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
 7 8 9 14 15 25 26 57 58

CON'T
 01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 10 | 0 | 3 | 6 | 9 | 7 | 1 | 1 | 1 | 8 | 8 | 1 | 8 | 1 | 2 | 2 | 3 | 8 | 1 | 9
 7 8 50 51 58 59 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | While in mode 5, both residual heat removal (ND) loops were rendered inoperable when Construction personnel, working in accordance with a shutdown
 03 | request, disconnected the pressurizer vapor space temperature sensor signal
 04 | cable causing an inlet isolation valve to close. This violates Tech. Spec.
 05 | 3.4.1.4 which is reportable pursuant to Tech. Spec. 6.9.1.3(b) and is similar
 06 | to previous RO's No. 369/81-72 and 81-129. This incident had no effect on the
 07 | health and safety of the public.
 7 8 9 80

09 | SYSTEM CGOE | C | F | 11 | CAUSE CODE | A | 12 | CAUSE SUBCODE | A | 13 | COMPONENT CODE | V | A | L | V | E | X | 14 | COMP. SUBCODE | E | 15 | VALVE SUBCODE | D | 15
 7 8 9 10 11 12 13 18 19 20
 17 | LER/RO REPORT NUMBER | 8 | 1 | 21 | 22 | SEQUENTIAL REPORT NO. | 1 | 8 | 5 | 24 | 26 | OCCURRENCE CODE | 0 | 3 | 28 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32
 ACTION TAKEN | E | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 10 | 0 | 0 | 37 | ATTACHMENT SUBMITTED | Y | 23 | NPRO-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | L | 25 | COMPONENT MANUFACTURER | Z | 9 | 9 | 9 | 26
 33 34 35 36 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The work associated with the shutdown request was begun before the step was
 11 | reached in the controlling procedure which would have rendered the two resi-
 12 | dual heat removal system suction valves inoperable. The signal cable was
 13 | reconnected, the valve reopened, and the system declared operational. Opera-
 14 | tors have been cautioned about the possibilities of ND isolation due to actuation
 7 8 9 80

15 | FACILITY STATUS | X | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | mode 5 | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Alarms | 32
 7 8 9 10 12 13 44 46 48 80
 16 | ACTIVITY CONTENT | Z | 33 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36
 7 8 9 10 11 44 45 80
 17 | PERSONNEL EXPOSURES | NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39
 7 8 9 11 12 13 80
 18 | PERSONNEL INJURIES | NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41
 7 8 9 11 12 80
 19 | LOSS OF OR DAMAGE TO FACILITY | TYPE | Z | 42 | DESCRIPTION | N/A | 43
 7 8 9 10 80
 20 | PUBLICITY | ISSUED | N | 44 | DESCRIPTION | N/A | 45
 7 8 9 10 80

NAME OF PREPARER Phillip B. Nardoci

PHONE: (704) 373-7432