MORTHEAST UTILITIES

THE CONNECT CUT SIGHT AND POWER COMPANY
THE HARTFESSO EXCTRIC FOR COMPANY
WISTERN MASSACHISTITS SLEETING COMPANY
WISTERN MASSACHISTITS SLEETING COMPANY
NORTHERAT LYTH THIS SERVICE COMPANY
NORTHERAT LYTH THIS SERVICE COMPANY
NORTHERAT MASSACRA ENDROT COMPANY

General Offices • Selden Street, Berlin, Connecticut

P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 669 6911

December 17, 1981

Docket No. 50-423 AEC-MP3-257 B10354

Mr. Ronald C. Haynes
Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406



Reference: (1) W. G. Fee/W. G. Counsil letter to B. H. Grier, dated March 27, 1981.

Gentlemen:

Millstone Nuclear Power Station, Unit No. 3
Reporting of Potential Significant Deficiencies
in Design and Construction

As required by Title 10, Code of Federal Regulations Part 50, Paragraph 55(e), on February 24, 1981 our Mr. B. L. Carlson reported to your Mr. R. A. Feil a potential significant deficiency in the construction of Millstone Unit No. 3. The potential significant deficiency involved the use of welding procedures in applications for which they had not been qualified. Reference (1) was the required thirty day report, and it indicated the potential significant deficiency was under a continuing investigation. That investigation has now been completed and Northeast Nuclear Energy Company has concluded that under the guidelines of 10CFR50.55(e) a potential significant deficiency does not exist.

During fabrication of the Millstone Unit No. 3 containment liner, Graver Energy Systems qualified certain weld procedures for particular materials (P-No. Group No.), but then misapplied these procedures to other materials (wrong Group No.). A sub-vendor (Wooley) was also involved with two of the procedures in question. The primary concern was whether or not the procedures which were used could reduce the materials toughness of the containment liner.

Through meetings, procedure reviews and specimen testing, it has been determined that the weld's meet the appropriate ASME III code and specification requirements. No corrective action is required for the subject welds and had this situation gone undetected the safety of operations at the plant would not have been adversely affected.

8201060432 811217 PDR ADDCK 05000423 S PDR

1621/p

We trust this report provides you with sufficient detail describing our disposition of the subject potential significant deficiency in construction.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

W. G. Counsil

Senior Vice President

W. G. Counsi

By J. P. Cagnetta

Vice President Auclear and Environmental Engineering

cc: Mr. James H. Sniezek, Director
Division of Resident and Regional
Reactor Inspection
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Allerti p

D 8 11 10