



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

VOGLEWEDE  
READING  
FILE

JAN 11 1980

Mary G. White, ANS Technical Program Chairman  
Attn: Ruth Farmakes  
American Nuclear Society  
555 North Kensington Avenue  
LaGrange Park, Illinois 60526

Dear Ms. White:

In accordance with instructions provided to me by the Chairman of the ANS Reactor Physics Division, I have enclosed four copies of a paper summary entitled "Lessons Learned from TMI In-Reactor Instrumentation: An NRC Viewpoint." Summary Cover Sheets for this paper are also included. This paper is being submitted for presentation at the 1980 ANS Annual Meeting.

Sincerely yours,

A handwritten signature in cursive script that reads "John C. Voglewede".

John C. Voglewede  
Core Performance Branch  
Division of Systems Safety

cc: R. C. Kryter, ORNL

8201110215 810403  
PDR FOIA  
MADDENBO-515 PDR

# SUMMARY COVER SHEET

CONTRIBUTED PAPER

INVITED PAPER

ORIGINAL AND THREE COPIES REQUIRED

TITLE: Lessons Learned from TMI In-Reactor Instrumentation: An NRC Viewpoint

AUTHOR(S): (List authors in the proper order and exactly as they are to be published. PLACE AN ASTERISK AFTER EACH AUTHOR WHO IS AN ANS MEMBER; AN "S" AFTER STUDENT AUTHOR.)

1. John C. Voglewede \*

2.

3.

AFFILIATION(S): (List corresponding author's affiliation and complete mailing address.)

1. Division of Systems Safety, U.S. Nuclear Regulatory Commission,  
2. Washington, D.C. 20555

3.

Indicate number of author to whom correspondence should be addressed 1, and complete page 4.

To whom should the page charge be billed? U.S. Nuclear Regulatory Commission

Preferred: Attach purchase order with appropriate purchase order number to original copy of the summary.

## FOR CONTRIBUTED SUMMARY:

Identify ANS Division or Technical Group having cognizance of your subject \_\_\_\_\_

In which subject category (from page 3) do you feel this summary belongs? \_\_\_\_\_

Alternative Category: \_\_\_\_\_

Has the substance of this summary been presented or published previously (including U.S. DOE or equivalent reports)?

YES NO Give details \_\_\_\_\_

Has the paper been submitted for publication in a technical journal?

YES NO Give details \_\_\_\_\_

Have you presented related papers?

YES NO Give details \_\_\_\_\_

Has this summary been approved for publication by your institution or company?

YES NO Give details \_\_\_\_\_

## FOR INVITED SUMMARY:

Which ANS Division or Technical Group invited you? Reactor Physics Division

Person who invited you M. Becker/R.C. Kryter Session No. 14.3

## FOR CONTRIBUTED OR INVITED SUMMARY:

Number of: Pages 3 Tables 0 Figures 0

Word Count: Text 750 + (No. of figures plus tables) × 150 \_\_\_\_\_ + (No. of lines of equations × 10) \_\_\_\_\_  
Total 750

Original line drawings or glossy black-and-white prints of each figure must be attached to original.

A COMPLETED SUMMARY COVER SHEET, TOGETHER WITH THE INFORMATION REQUESTED ON PAGE 4, MUST BE ATTACHED TO EACH OF THE FOUR SETS OF THE SUMMARY. Please have copies made to complete your four sets.

FILING AND MAILING INFORMATION  
(Original and 3 copies required)

Name and full mailing address of author  
to whom correspondence should be sent.  
(Type or print legibly - form used for mailing.)

LOG # \_\_\_\_\_

..... John C. Voglewede .....
..... Division of Systems Safety .....
..... U.S. Nuclear Regulatory Commission .....
..... Washington, D. C. 20555 .....

Telephone:	
Commercial:	301-492-7603
FTS:	492-7603

Title of Summary Lessons Learned from TMI In-Reactor Instrumentation: An NRC Viewpoint

This is to acknowledge receipt of your summary. Please use the log number above in future correspondence.

This summary will be considered for inclusion in the program of the American Nuclear Society's 1980 Annual Meeting, Las Vegas, Nevada, June 8 - 13, 1980. Another copy of this form will be sent to you about February 13, 1980.

Your paper has been reviewed and:

- |   |   |
|---|---|
| <input type="checkbox"/> 1. Accepted for presentation at the 1980 Annual Meeting. (See Attached Instructions) | <input type="checkbox"/> 3. It is suggested that your summary be combined with the summary referenced as Log # _____ (See Attachment) |
| <input type="checkbox"/> 2. It is suggested that your summary be revised. (See Attachment)                    | <input type="checkbox"/> 4. Rejected. (See Attached Comments)   |

Your paper is being returned without review because:

- |  |   |
|--|---|
| <input type="checkbox"/> 1. It was received after the deadline date. | <input type="checkbox"/> 2. It significantly exceeds the word limit of 900 words. |
|--|---|

In all correspondence regarding your summary, please refer to the Log Number shown above.

Thank you for submitting this summary.

Sincerely,

Mary G. White  
ANS Technical Program Chairman  
1980 Annual Meeting

# LESSONS LEARNED FROM TMI IN-REACTOR INSTRUMENTATION

## AN NRC VIEWPOINT

John C. Voglewede  
Division of Systems Safety  
U.S. Nuclear Regulatory Commission

During the TMI-2 accident, a condition of inadequate core cooling existed and was not recognized for many hours. This resulted from a combination of factors including insufficient indicating range for existing instrumentation, unfavorable location of instrument readout, and perhaps insufficient instrumentation. The Nuclear Regulatory Commission staff has analyzed each of these perceived deficiencies and has made a number of new regulatory requirements and technical recommendations.

The regulatory viewpoint of the lessons learned from the in-reactor instrumentation at TMI-2 is similar to that of the owner, the reactor vendor, and the nuclear industry as a whole. That is, the in-reactor instrumentation played a prominent role during the first few hours of the accident as well as the period of time leading to cold shutdown of the plant. Because of this, the NRC Lessons Learned Task Force concluded that the as-designed and field-modified instruments at TMI-2 provided sufficient information to indicate reduced reactor coolant level, core voiding, and deteriorated core thermal conditions.

Three Mile Island was one of the best instrumented reactors in operation because of the large number of in-core thermocouples and other features. Unfortunately, these positive features did not result in the prompt recognition of, and the rapid recovery from, a condition of inadequate core cooling.

In response to this and other findings from the Three Mile Island accident, the NRC staff initiated a number of short-term requirements, based on "TMI-2 Lessons Learned Task Force Status Report and Short-Term Recommendations" (NUREG-0578). The status of the industry response concerning in-reactor instrumentation is

summarized in this presentation, and the Metropolitan Edison Restart Submittal on Three Mile Island Unit 1 is used as an example of the industry response.

Metropolitan Edison, like other utilities, is required to review its present in-reactor instrumentation to determine how the condition of reduced coolant level and core voiding can be detected. The existing instruments examined by Metropolitan Edison measure coolant temperature, flow, and pressure as well as neutron flux and motor current of the coolant pumps. The staff supports such diversity. However, these instruments existed at TMI-2 at the time of the accident. New instruments, such as the PWR vessel coolant level detector, have also been required and long-term improvements in other areas are being actively pursued by the staff. The results of these efforts, however, have not yet been implemented.

With regard to existing instrumentation, the staff has noted that many instruments at TMI-2 lacked sufficient range of indication. A notable example was the range of the core exit thermocouples. As a result, Metropolitan Edison has extended the indicating range of these thermocouples as well as the indicating range of the reactor outlet resistance temperature detectors (RTDs) in the Unit 1 facility. This was done without replacing the sensors. Access to the in-core thermocouple signals from outside of the containment building has also been provided. This feature did not exist on Unit 1 at the time of the Unit 2 accident. The indicating range of these instruments now encompasses the physical limitations of the sensor rather than the expected response of the device during normal operation. The change from expected to extended instrument range reflects the staff position in the proposed revision to Regulatory Guide 1.97, "Instrumentation for Light Water Cooled Nuclear Power Plants to Access Plant Conditions During and Following an Accident" issued December 4, 1979.

All PWR owners are also required to install a saturation meter in the control room to provide an indication of the degree of subcooling in the primary coolant. However, the use of in-core thermocouples, extended range reactor outlet temperature RTDs, and the new saturation meter are enhancements of existing instruments. The staff previously concluded that reduced coolant level and the existence of core voiding could be determined with these instruments. Longer term improvements in the instrumentation will make this determination easier, provided the operator is aware of the available information and interprets it correctly.

An important lesson learned from TMI-2 on the subject of in-reactor instrumentation is that the operator must be made aware of the available information and must know how to interpret it correctly. Marked improvement in an operator's ability to quickly recognize a condition of inadequate core cooling, and his ability to act upon this information, will, in my judgement, lie more with improvement to the operator's training and instruction than with improvement of the instrumentation. However, both approaches have been required by the NRC to ensure that conditions of inadequate core cooling do not go undetected in the future.