BOSTON EDISON COMPANY

GENERAL OFFICES 800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

A. V. MORISI
MANAGER
NUCLEAR OPERATIONS SUPPORT DEPARTMENT

January 5, 1982

BECo. Ltr. #82-2

Mr. Thomas A. Ippolito, Chief Operating Reactors Branch #2 Division of Licensing Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D. C. 20555

> License No. DPR-35 Docket No. 50-293

Response to Request for Information on Diesel Generators (U.S.I. A-44)

Reference (A): NRC Letter of July 20, 1981 from Mr. Thomas A. Ippolito to Mr. A. V. Moris. (BECo. Ltr. #1.81.198)

Dear Sir:

In Reference (A), the NRL requested that we complete the question re attached to it. Boston Edison believes the attached document satisfies that request.

In preparing this response we used, in addition to Licensee Event Reports, the following sources of information:

- System #61 VISI Records -- Maintenance Machine history record files kept on the Diesel Generators and associated equipment - 1972-1980.
- (2) System #61 Maintenance Requests 1972-1980.
- (3) System #61 PDCR's -- Plant Design Changes on Diesels or associated equipment 1972-1980.
- (4) Watch Engineer Log Books -- This is the daily log of plant happenings kept by the Watch Engineer 1972-1980.
- (5) 345 kV Disturbances -- This is a list of disturbances associated with the 345 kV Grid. This list is maintained by the Nuclear Engineering Department (Boston Edison). (Loss of 345 kV requires Diesel's to start.) This is from 1972-1980.
- (6) Surveillance 8.9.1 Data Results -- Routine one hour, 100% load test performed on the Diesel Generators. These records are from 1976 1980. Note: This test was performed on a routine weekly basis through 1978. From 1979 to the present, this test is performed every other week. It is also performed after diesel maintenance has been completed.

8201110583 820105 PDR ADOCK 05000293 P PDR A001

BOSTON EDISON COMPANY

Mr. Thomas A. Ippolito, Chief January 5, 1982 Page 2

- (7) Diesel Report Book 1 & 2 -- These are two books that are kept in the office of the Station Electrical Engineer. They are records of unusual happenings, annual overhaul reports, special reports, etc. The Diesel consultant to Boston Edison maintains these books with the assistance of the Station Electrical Engineer and they are a complete history of the Diesels.
- (8) Surveillance 8.M.3.1.A Data -- This is an annual test performed on the Diesel Generators. This test proves the ability of the Diesel Generators to automatically start and accept their ECCS loads with a simulated loss of AC Power and LOCA.

The information provided in the attached Tables 1, 2 and 3 is for the years 1976 through 1980. The information in Table 4 is from the year the reactor went critical, taken to be 1972, through 1980.

We believe this response addresses your request. Should you require further information regarding this issue, please contact us.

Very truly yours,

Attachments: Table #1 - For calendar years 1976 through 1980

Table #2 - For calendar years 1976 through 1980 Table #3 - For calendar years 1975 through 1980

Note: 1975 necessary because of LER Abstract No. 11

John M. Fult

Table #4 - From 1972 through 1980

Diesel Generator Operations Onta Calendar Year 1976

Enclosure	- Page 1	
"Lant Name	Pilgrim	
Unit No.		

Tech. Spec. Req'd Test One Hour at 100% Automatic Starting, Load Sequencing, with simulated loss of off-site A.C. Power	A B A B	54 55	0 0	100% 100% 75% 75%		LER not applicable. Diesel had been tagged out of service. Prior to returning Diesel to service, normal routine surveillance test required to be performed; it was while this test
Automatic Starting, Load Sequencing, with simulated loss of off-site A.C. Power	A B	1	0	75%		returning Diesel to service, normal routine surveillance test required to be performed; it was while this test
Automatic Starting, Load Sequencing, with simulated loss of off-site A.C. Power	B A	1		75%		routine surveillance test required to be performed; it was while this test
Load Sequencing, with simulated loss of off-site A.C. Power	B A	1				be performed; it was while this test
Load Sequencing, with simulated loss of off-site A.C. Power	B A	1				
Load Sequencing, with simulated loss of off-site A.C. Power	B A	1	0			
off-site A.C. Power	-		-			was being performed the Diesel was
Auto Start per Bup	-	-				slow to start.
MILLO STAFF DOF ROR	-	4 2	0	0		
		2	0	0		
Auto start per Core	A	2	0	0	Laborated array of the latest and the latest array of the latest a	
	В	2	0	0		
DG Actual Demand						
Starts not for Testing	A	1	0	20%		
and the second s	В	1	0	15%		
				1 1		
-		-	-			
L.						
Hiscellaneous Tests (Specify Type)						
_						
_						

Diesel Cenerator Operation. Data Calcudar Year 1977

TABLE 1

-

Frant Name Pilgrim

Unit No.

(Refer to ettached LERs or Table 3) Identification of Pallure Before Stop For Duration of Run Ench DO Pailure Loading of DC (KH) Percent 100% 1008 758 758 208 158 q 0 Pat Inte. Number 0 0 0 0 0 0 0 0 0 0 Starte 8 Humber -62 61 Jo 8 2 110. BB K 8 4 K B B B Operation, 6 scheduled simulated loss of off-Tech. Spec Req'd Test Load Sequencing, with Core Spray Logic Auto Automatic Starting & site A.C. Power with RIIR Logic Auto Start Miscellancors Tests One Hour at 100% DG Actual Demand Starts not for (Specify Type) Reason for ING Testing Start LOCA

Diesel Generator Operation. Data Calendar Year 1978

Fluit Name Pilgrim Unit No.

		-	-	-		A STATE OF THE PARTY OF THE PAR
Reason for DG		Mumber	Number	Percent	Duration of Run.	
Operation, & scheduled	DQ.	Jo	of	Loading of	Defore Stop For	Identification of Pailure
Tech. Spec Rea'd Test	1	2000	Tallotte.	1	Cach at railure	
	1	00		1008	CONTRACTOR OF STREET,	DEN ADSTRACT #/
One Hour at 1001	B	09	12	1003		LER Abstract #8
Automatic Starting &	4	-	10	75.0		
Load Sequencing with	B	-	T	758		
Simulated Loss of			T			The second secon
off-site A.C. Power			1	-		
	1		I			
	1		Ī		And the second s	
Auto Start Per RHR	A	2	0	0		
Logic	В	2	0	0		
Auto Start Core Spray	K	2	0	0		
Logic	В	2	0	0		
Starts not for						
Testing	K	2	0	0		
	В	2	0	0		
	1					
	1					
Hiscellancous Tests						
(Specify Type)	1	-	İ	1		
	1	-	1			
	T		1			
	1	-				
	-					
	1					
_	1					

Diesel Generator Operations Data Calendar Year 1979

Enclosure 1 - Page 1 Flunt Name Pilgrim Unit No.

	-			-	- 1	
	_	Humber	Number	Percent	Duration of Run	
Operation, 6 scheduled	_	Jo.	Jo .	-	Acfore Stop For	Identification of Failure
Duration of Run	No	Starte	Fallure,	DC (KN)	Each DG Fallure	(Refer to attached L.F.Rs or Table 3)
Tech. Spec Req'd Teet	<	3.7	0			
One Hour at 100%	В	38	0			
Auto Start Per RHR	A	2	0			Note: LER Abstract #5
Logic	В	2	0			Diesel did no
						er test annur
					And the second section of the second	for a problem one description
			-			a program was observed.
The state of the s	1.	1	1		And the second s	
Auto start Per Core	-	7	0	-		
Spray Logic	B	2	0			
					The state of the state of the state of	
IN. Actual Demand				-		
Testing	A	2	0	20%		
	В	2	0	15%		
					American mention of the	
Hiscellaneous Tasta						
(Specify Type)			1			
	-	-	1			
		-	1			
	-					

Figure 1 - Page 1

TABLE 1

Diesel Generator Operation, Data Calendar Year 1980

(Refer to attached L.Rs or Table 3) Identification of Pailure LER Abstract #2 LER Abstract #3 Before Stop For Duration of Run Each DG Pailure Loading of Percent DC (KM) 100/110% 100/110% 1008 758 75% 20% 15% Fallure, Number of 0 0 d 0 0 0 0 0 2 0 Humber Starts 43 35 jo No. K B В AB A K 8 8 B Operation, 6 scheduled Tech. Spec. Reg'd Test Simulated Loss of off-24 Hr. continuous test Tech. Spec Req'd Test Load Sequencing with Automatic Starting & site A.C. Power with Hiscellaneous Tests Auto Start Per RHR at 100% and 1 hr. One Hour at 100% DG Actual Demand Purntion of Run Starts not for (Specify Type) Auto Start Per Reason for DC Core Spray Testing at 110% Logic LOCA

Table 2

Diosel Generator Scheduled Downtime Record Calendar Year 1976

5

Plant Name Pilgrim Unit No. 1

					llours	of Down	ntima				
Resson for		React	or shu	tdown		Re	octor n	ot shu	tdown		Comments
Downt Ime	DCI A	DCF B	DCI	DCF	DCI	DEF	DC)	DCI	DCI	DCI	
Scheduled Haintenance Refueling Outage	720	120									Refuel Outage Dates 1/29/76-6/1/76
Preventive maintenance Annual checks, Repairs, Modifications etc.											
Unscheduled Maintenance											
Exhaust Bellows Leak						12					Replaced Exhaust Bellows that was leaking at the weld
Engine would not normally shutdown		8									Replaced Gov. Dump Valve Coii
Sticky Turbo Assist		8									Cleaned Valves
Exhaust Bellows Leak							12				Replaced Exhaust Bellows that was leaking at the weld

Time DG is unavailable for emergency service because of required tests Diesel Generator Logic dictates that emergency conditions overide normal routine testing; therefore, time available is N/A.

During tests when the emergency logic is prohibited from performing its function, then the Diesel/ Generator is considered to be unavailable and the hours are reflected above in the downtime.

Diesel Generator Scheduled Downtime Record Calendar Year 1977

Plank Name Pilgrim

					Hours	of Down	nrima			•	
Reason for		React	or shu	tdown		Res	actor r	ot shu	tdown		Comments
Downt Ime	DCF	DC/ B	DCI	DCI	DCF	DX:	DC/ B	DCI	DCI	DCI	
Scheduled Maintenance Refueling Outage Preventive maintenance Annual checks, Repairs Modification, etc.		800									Refuel Outage Dates 8/6/77-12/12/77
Installed expansion water tank							30				To allow testing of the coolant system
Relocated Ventilation Cable & Dampers						84	24				To allow pre-work on modifications scheduled to be done during outage
Inspection of Radiator Fan Blades Unscheduled Maintenance						30	30				Engineering Dept. had requested hubs of blades be inspected
Leaking Fuel Gauge Line							5				Leak had been observed during routine test and line was replaced
Time DG is unavailable for emergency service because of required tests			N/A				N/A				See 1976 Table 2

Diesel Generator Scheduled Downtime Record Calendar Year 1978

Enclosure 1 - Page 2
Plant Name Pilgrim
Unit No. 1

	_				llours	of Dow	entime				
Renson L.T.			tor shu			Re	actor	not shu	tdown		Connents
	DC	DC/B	DCA	TUCK	DC	DC		DCI		DCF	
Scheduled Haintenance			THE				-				No Refueling Outage
Radiator Fan Blade Inspection	72										
Unscheduled Maintenance Belt-Fuel Oil Pp Belt-Fuel Oil Pp Belt-Fuel Oil Pp	6					6					Shaft Driven Fuel Oil Pp "V" Belts were failing (Breaking). Changed belt and type fastener.
Engine sluggish							48				
Engine would not											Replaced Govenor
shutdown normally							4		1		Replaced Gov. Dump Valve Coil
Failed Gen. Exciter							46				Replaced failed electrical components
Fuel oil leak						6					Gen. had been closed in out of sync. Replaced leaking fuel oil crossover "T" connection
Generator failure		384				j					
Engine sluggish						4					Rewound Generator and replaced Govenor Replaced Gov. oil
Time DG is unavoilable for emergency service secouse of required tests			N/A				N/A				See 1976 Table 2 comment

Diesel Generator Scheduled Downtime Record Calendar Year 1979

Plant Name Pilgrim Unit No. 1

Rea on for	-			THE RESERVE AND ADDRESS OF THE PERSON NAMED IN	Hours	of Dos	mtime				
Downt Ime	DCF		or shu			Re	actor	not shu	Edown		-
	A	B	DG	DCF	DCI	DE	DCI	DCF		DCI	Comments
Scheduled Haintenance			4.			1	B			-	NO PERMIT NA CONTRACTOR
Engine Sluggish						4					NO REFUELING OUTAGE
Engine Sluogish						10					Replaced Gov. 0il
Locse Bolts							4		1		Replaced Gov.
Pre-Lube Trip		4									Indicating Cock Bolts Tightened
Loose Belt						4					Faulty connection in Motor Terminal Box.
UNSCHEDULED MAINTENANCE											Fuel Oil Pp V Belt slipping
Engine could not be			1								
ormally shutdown				- 1		1	12				Govenor Dump Valve Nut had worked lo
ngine could not be ormally shutdown	1						6				was to roughenthe threads
										i	Govenor Dump Valve Nut had again work loose. Repair this time was to drill hole and use stainless steel wire to
eceived Generator										s	ecure.
rotective Relay peration	1						24		1		lectrical checks were performed and eason for the relay operation could etermined
ne DC 1s unavailable		- -	-	- -	- -	-	-				
emergency service		N,	/A				N/A				See 1976 Table 2

Diesel Generator Scheduled Downtime Record Calendar Year 1980

Enclosure 1 - Page 2
Plant Name Pilgrim
Unit No. 1

					Hours	of Dow	ntime				
Reason for Downtime		Contract of the last of the la	or shu	tdown		77		not shu	tdown		
	DC!	B	DCI	DCF	DC	DE	DC	and the same of th	DCI	DCF	Comments
Scheduled Maintenauce						A	B	-			
REFUELING OUTAGE											REFUELING OUTAGE DATES
Preventive maintenance Annual checks, Repairs, Modifications, etc.	240	1082									1/5/80-5/19/80
Generator Electric	8										Repaired Heater
UNSCHEDULED MAINTENANCE											
Fuel Oil leak						6					Replaced leaking Fuel Oil
											crossover "T" connection
									1		
							1				
ne DG is unavoilable r emergency service cause of required		N	/A				N/A		1	1	See 1976 Table 2

Diesel Generator Unscheduled Downtone Record Calendar Year 1975

EA Abstract N. Refer to attel	now	mtime lloui	ra		Comments - If any of the
d LER Abstract	s) Total	frouble- shooting	Parts,Del	Repair/	Comments - If any of the reported failures would not have been a failure under emergency conditions, please explain here. Refer to attached LERs or the failures listed in Table 1.
11	6	30%	N/A	70%	During routine surveillance testing, the engine coming up to speed was noticed to be slower than normal. The trouble was traced to the turb assist valves which were sticking. The valves were cleaned and the engine starting time tested. Note: This LER is for 1975 but was part of enclosure #2 supplied with the Information Request.
			İ		

Diesel Gunerator Unschedulud Down. Ime Record Calendar Year 19 76

LER Abstract No (Refer to attel)	the second secon	mtime lloui	ra		Comments - If any of the second
ed LER Abstract	e) Houre	frouble- shooting	'arta, Del	- Repair/	Comments - If any of the reported failures would not have been a failure under emergency conditions, please explain here. Refer to attached LERs or the failures listed in Table 1.
9	12	20%	204	60%	During routine surveillance testing of Diesel "B", smoke was observed to be coming out of the exhaust manifold area. A weld on a Bellows Connector which is part of the exhaust manifold had failed. The Bellows Connector was replaced. Note: The failure of this weld on the Bellows Connector would not have prevented the diesel from performing its designed function.
10	12	20%	201	- 1	During routine surveillance testing of Diesel "A", an exhaust manifol leak was reported. A weld on a Bellows Connector which is part of the exhaust manifold had wiled. The Bellows Connector was replaced. Note: The failure of this weld on the Bellows Connector would not have prevented the diesel from performing its function.

Diesel Generator Unacheduled Downson Record Calendar Year 1977

Plent Nome Pilgrim Unit No. 1

I.F.R Abstract No (Refer to ettel)	Assessment of the Control of the Con	ntime Hous	ra		Comments - If any of the reported failures would not have been a
d LER Abstract	a) Hours	frouble- shooting	Partu,Del	Repair/	failure under emergency conditions, please explain here. Refer to attached LERs or the failures listed in Table 1.
6	N/A	N/A	N/A	N/A	This LER was part of enclosure #2 supplied with the information requestetter. It does not have anything to do with the reliability of the Diesels and should be disregarded for this study

Diesel Generator Unacheduled Downtime Record Calendar Year 1978

Refer to attel		mtime Hou			Comments - If any of the
ed LER Abetracis	s) Total	Trouble- shooting	'arta,Del	Repair/	Comments - If any of the reported failures would not have been a failure under emergency condition, please explain here. Refer to attached LERs or the failures listed in Table 1
,	400	10%	30%	60%	During routine surveillance testing of Diesel "B", the Generator output breaker tripped. Investigation showed that stator of the Generator had shorted to ground. The stator was rewound.
8	48	40%	10%		During routine surveillance testing of Diesel "B", the Generator was inadvertently thrown in out of synchronization. Investigation showed that various electrical components within the exciter & regulator had failed. Failed components were replaced and the 1 hours.

Diesel Constant Unscheduled Downsine Record Calender Sear 1979

LER Abstract No (Refer to attel)		ntime llou			Comments - If any of the recent
ed LER Abstrac	s) Total	shooting	'arts, Del	Repair/	failure under emergency conditions, please explain here. Refer to attached LERs or the failures listed in Table 1.
5	24	1000			A routine starting surveillance had been performed on "A" Diesel an after the surveillance was performed annunciation was observed showing that the generator output breaker was tripped. The surveillance test only required that the diesel be observed to start and was not required to be loaded. However, an investigation was made and tests performed to show that a problem did not exist. When all tests proved positive, the diesel was started, loaded and run for 1 hour at 100% full load before being returned to service.

Diesel Generator Unscheduled Downtime Record Calendar Text 1980

Enclosure | - Page 3
Plant Name Pilgrim
Unit No. 1

REK Abstract No bounts		ntime Hou	re.		failure under contracted failures would not have been a	
ed LER Abetraci	s) Total	freuble- abouting	Parca, net	Repair/	Refer to attached LERs or the failures listed in Table 1.	
/ 1	N/A	N/A	N/A	N/A	This LER was part of enclosure #2 supplied with the information request letter. As stated in the LPR, the reason for the tree.	
3/1 KG					This LER is not related to the reliability of the Diesels and should be disregarded for this study.	
2	6	N/A	50%	50%	While performing a routine surveillance test on Diesel "A" a fuel oil leak was observed. The failed component was a crossover "T" connection in the fuel line and was replaced.	
3	102	25%	25%		A special test on "A" Diesel was being performed as requested by the NRC. This test included operating the unit for 24 continuous hours at 100% full load and for one hour during the test, the unit is to be tenance overhaul. Three hours after the initial state of the special state	
				6	After restoration of the fuel oil transfer pump, the test was restarted and transferred over to its backup. It was decided to stop the test, replace the belt and restart the test he next day.	
				b T	The next day the test was started and after 21 hours the unit tripped because of a transformer failure. The transformer and other electrical components which had failed were eplaced and after the 24 hour test was performed, the unit was eclared operable.	
	N/A	N/A	N/A	N/A T	his LER was part of enclosure #2 supplied with the information request etter. It does not have anything to do with the reliability of the lesels and should be disregarded for this study.	

Onsite Emergency Diesel Generator and Auxiliary Equipment Hodification Record Enclosure 1 - Page 4
Plant Name Pilgrim
Unit No. 1

Equipment or	Date of	Auxiliary Equipment Hodification Re	cord Unit No. Pilgrim
procedure modified	Hod.	Reason for Hodification and Desired Improvement	Description of Modification
A & B Diesel Exhaust Manifold Pipes & Bellows	1977	Cracks were being experienced on the welds of the Exhaust Manifold Pipes and the Bellows	1: Changed the welding specifications so that all exhaust manifold welds would use filler metal (Inconel 625)
			2: Changed Bellows to Incomel type 3. Changed exhaust manifold support assembly to minimize vibration
A & B Diesel	April	Hub of Radiator Fan Blades subjected	4. Replaced all exhaust manifold pipes & Bellows to new style
Radiator Fan Blades	1977	to high torsional stresses and the Engineering Dept. requested that they be checked.	Procedure written that requires that hub of blade be examined on a routine basis. (Dye Penetration) Proc. 3.M.4-36
A & B Generator Exciter, Regulator and Circuit Breaker Logic	Dec.	While performing a routine test a failure of Diodes in the regulator circuit cascaded into failures of other electrical components in the exciter and the regulator.	a: Replaced (3) saturable core transformers b: Replaced (2) fuses on primary transformer with 1: c: Replaced (2) fuses in regulator with solid links d: Removed diodes that were unnecessary e: Installed a time delay relay to remove race of relay contacts
		Investigation of this failure resulted in desired changes to improve the reliability during voltage transients and the elimination of a race of relay contacts in the generator breaker logic.	Total Contacts

Onsite Emergency Diesel Generator and Auxiliary Equipment Hoditication Record

Enclosure 1 - Page 4
Plant Name Pilgrim
Unit No. 1

Equipment or procedure modified	Date of Hod.	Resson for Hodification and Desired Improvement	Description of Hodification
A & B Generator Relay Protection	1977 Aug. thru Dec.	To provide antimotoring protection during tests when the Generator is tied to the system.	Installed Reverse Power Relays to protect against antimotoring during test.
A & B Diesel Exhaust Ducts	1977 Aug. thru Dec.	Moisture entrapment was causing corrosion on the ducts.	Modified the Exhaust Pipe top rain shield and repaire the Missle Shield.
A & B Diesel Air Discharge Plenum	1977 Aug. thru Dec.	The Diesel Engine Room Air discharge route was restrictive. This resulted in the cooling radiators being inefficient.	Changed the discharge plenums so as to eliminate the air restrictions and increase the cooling radiators efficiency.
A& B Diesel Combustion Air Intake Filter	1977 Aug. thru Dec.	Air supplied to the Diesel Combustion Air Intake Filter was required to pass over the hot running diesel. This would result in the air absorbing heat and supplying hot air, which resulted in the engines running hotter than was necessary.	Installed the necessary piping to relocate the engine Combustion Air Intake Filter so that the engine received intake air at ambient temp.
A & B Diesel Fuel Oil Pp. (V Belt)	1978	Shaft Driven (V Belts) were failing at the connection where they were spliced.	Changed to a new style belt and a different type connection.

Onsite Emergency Diesel Generator and Auxiliary Equipment Hodification Record Plant Name Pilgrim

Equipment or procedure modified	Date of Hod.	Remon for Hodification and Desired Improvement	Description of Hodification
A & B Diesel Govenor Solenoid Coil	1978	Normally energized coils when engine not running were failing. This resulted in inability to shutdown engines electrically after they were started. The coils were 125V rating and being maintained at 134V.	Replaced 125V rating coil with 140V rating coil.
A & B Diesel Generator Monthly Surv.	Jan. 1979	Surveillance test as required by Tech. Specs. is to be run once a month. Per administrative decision, this was being performed once a week. It was felt the test should be cut down to every other week and this would be better for the diesels and their associated equipment.	Per administrative directive, Testing Surveillance performed every other week as opposed to once a week. Note: Consideration is being given to going back to once per week testing and also to run the unit for 2 hours at approximately 75% and once a month at 100% for one hour to meet the Tech. Spec. requirement.
A & B Diesel Cooling Water Jacket Expansion Tanks	1980	The location (height) of the expansion tank was at a level (low) that on fast starts of the engine dir could be entrapped into the cooling water of the diesel.	Raised the expansion tank to a level that would preven air from being entrapped in the cooling water.

Onsite Emergency Diesel Generator and

Fquipment or procedure modified	Data of Hod,	Reason for Hodification and Desired Improvement	Description of Hodification
A & B Cnce Per Cycle Automatic Load Sequencing of the Diesels Proc. 8.M.3.1	1978 1979 1981	Changes in Technical Specifications required that the procedure be changed for documentation of testing, more testing, etc.	Changed/updated procedure as required.
A & B Diesel Generator Control Logic	1979 1980	Pire in the Cable Spreading Room. The control cables that run between the Diesel Room and the Main Control Room that pass thru the Cable Spreading Room were required to be isolated if a fire were to occur in the Cable Spreading Room.	Isolation switch installed in Diesel Room to isolate the Cable Spreading Room Cables and allow operator control from the Diesel Room.
A & B Diesel Air Start and Turb Assist Air Compressors	1980	The gasoline engines which are a back- up for the motors on the compressors were hard to start.	Installed 12V electric starting motors and batteries
A & B Diesel Fire Protection	1978	To comply with NRC Branch Position 9-5.1.	Installed: Pre-Acting Automatic Sprinkler System Smoke Detection System Heat Tracing on Sprinkler Piping