

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

C 1 | 0 | H | D | B | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T  
0 | 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 4 | 6 | 7 | 1 | 1 | 1 | 6 | 8 | 1 | 8 | 1 | 2 | 2 | 2 | 8 | 1 | 9  
7 8 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

0 2 | EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
(NP-33-81-89) On 11/16/81 the NSSS vendor, Babcock and Wilcox, confirmed that a new  
0 3 | analysis showed a general increase in the Reactor Protection System (RPS) instrument  
0 4 | string errors. This reduced the margin between the actual RPS trip setpoints in the  
0 5 | station and the trip points in the Tech Specs. This finding is reportable under T.S.  
0 6 | 6.9.1.9. There was no danger to the public or station personnel. The Cycle 2 Tech  
0 7 | Spec RPS trip setpoints still contained identifiable safety margins to offset the in-  
0 8 | creased instrument error such that the functional requirements of the system would  
7 8 9 have been met. 80

0 9 | SYSTEM CODE: I A (11) CAUSE CODE: B (12) CAUSE SUBCODE: A (13) COMPONENT CODE: Z Z Z Z Z Z (14) COMP. SUBCODE: Z (15) VALVE SUBCODE: Z (16)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 | LER NO REPORT NUMBER: 8 1 (21) EVENT YEAR: 8 1 (22) SEQUENTIAL REPORT NO.: 0 7 4 (24) OCCURRENCE CODE: 0 3 (28) REPORT TYPE: L (30) REVISION NO.: 1 (32)  
ACTION TAKEN: F (18) FUTURE ACTION: X (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0 0 0 0 (22) ATTACHMENT SUBMITTED: Y (23) NRPD-4 FORM SUB.: N (24) PRIME COMP. SUPPLIER: N (25) COMPONENT MANUFACTURER: B 0 1 5 (26)  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

1 0 | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 1 | This finding is due to additional testing on the RPS instruments which showed increased  
1 2 | errors. The actual RPS trip setpoints in the plant have been adjusted under Facility  
1 3 | Change Request 81-295 to account for the increased instrument errors. The vendor has  
1 4 | been authorized to perform an analysis to determine the new Technical Specification  
7 8 9 RPS trip setpoints for the upcoming Cycle 3 Technical Specification revisions. 80

1 5 | FACILITY STATUS: G (28) % POWER: 0 0 0 (29) OTHER STATUS: NA (30) METHOD OF DISCOVERY: D (31) DISCOVERY DESCRIPTION: Engineering analysis by Babcock & Wilcox (32)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE: Z (33) Z (34) NA (35) AMOUNT OF ACTIVITY: NA (35) LOCATION OF RELEASE: NA (36)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION: NA (39)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 (40) DESCRIPTION: NA (41)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) DESCRIPTION: NA (43)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 | PUBLICITY ISSUED: N (44) DESCRIPTION: NA (45)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8201110643 811222  
PDR ADOCK 0500034  
S PDR

NRC USE ONLY