UPDATE REPORT - PREVIOUS REPORT DATE 8/14/81 NRC FORM 366 U. S. NUCLEAR REGULATORY COMMISSION (7.77) LICENSEE EVENT REPORT CONTROL BLOCK: 1(1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 0 0 0 0 - 0 0 3 4 1 1 0 ALBRE 3 (2) 0 1 1 (4) LICENSE NUMBER LICENSEE CODE CON'T REPORT $L \bigcirc 0] 5] 0] 0] 2] 9] 6 \bigcirc 0] 7] 2] 3] 8] 1 \bigcirc 1]$ 0 1 2 3 1 8 1 (9) SOURCE DOCKET NUMBER EVENT DATE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During normal operation, containment atmosphere monitor (CAM) H_0, analyzer B 0 2 sample return valves could not be energized. See T.S. 3.7.H.2. H_0, analyzer A 0 3 [was operable. There was no danger to the health or safety of the public. There 0 4 | were no previous similar events. 6 80 CODE CAUSE CAUSE COMP VALVE COMPONENT CODE CODE SUBCODE A (11 S E (12) A (13) RÍ U1(14) E (15 Z (16) SEQUENTIAL OCCUPRENCE REVISION REFORT EVENT YEAR REPORT NO. CODE LER RO NO. REPORT 8 0 131 7 1 01 31 X 11 NUMBER 32 METHOD TAKEN ACTION NPRO-4 FORM SUB COMPONENT ATTACHMENT SUBMITTED PRIME COMP EFFECT ON PLANT HOURS (22) SUPPLIER Y 23 MANUFACTURER Y (24) L (25 X](81) B(21) 0 51 A(20) 0 4 V 10 13 10 A CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Valcore Engineering Corporation model V52630-529-1 solenoid assembly FSV-76-61 failed to operate due to a shorted bridge rectifier and coil. In addition, a [voltage supply wire was found loose due to a broken screw head. The solenoid 1 2 assembly was replaced and SI 4,7, D, 1, B-1(A) and SI 4,7. H were successfully completed. See attached for recurrence control. 80 METHOD OF DISCOVERY (20) POWER OTHER STATUS DISCOVERY DESCRIPTION (32) 100 NA. A (31) Operator observed ACTIVITY CONTENT 80 OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) 6 NA NA 80 PEPSONNEL EXPOSURES NUMBER 0 0 0 z 3 NA 80 PERSONNEL INJUNIES DESCRIPTION (41) NA 8201130192 811231 HO OSS OF OR DAMAGE TU FACILITY (43) PDR ADOCK 05000296 DESCRIPTION VDE PDR NA S Z (42) PUBLICITY DESCRIPTION (45) NRC USE ONLY NI(44 NA (205) 729-6134 80 Gene Holder NAME OF PREPARE

Tennessee Valley Authority Browns Ferry Nuclear Plant

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81037 R1 Technical Specification involved 3.7.H.2

Reported Under Technical Specification 6.7.2.b.2. *Date due NRC: NA Date of Occurrence 7/23/81 Time of Occurrence 0815 Unit 3

Identification and Description of Occurrence:

During normal operation, containment atmosphere monitor (CAM) H202 analyzer B sample return valves could not be energized. The solenoid lead wire and relays R2, R5, and 86-76-92A were damaged.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 99%.

Unit 3 at 100%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence: Solenoid coils assembly for FSV-76-67 failed to operate due to a shorted bridge rectifier and coil. A voltage supply wire was found loose due to a broken screw head. Inadequate design information lead to improper flex conduit connections at FSV-76-67 which allowed the solenoid assembly to be exposed to torus environment, permitting corrosion on bridge rectifier failure possibly prevented dissipation of heat and contributed to rectifier failure. Screw was probably overtorqued by manufacturer.

Analysis of Occurrence: There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action: Replaced FSV-76-67 solenoid assembly and telays R2, R5, and 86-76-92A. Flex connections for YSV-67-63. 76-65, and 76-67 sealed by taping with Scotch 70 and covered with Scotch 33+. Flex connector at body end of FSV-76-67 was replaced. SI-4.7.D.1.B-1(A) and 4.7.H were successfully completed. H20, valves inside the drywell on unit 3 will be checked during the next opportunity for drywell entry. Consideration is being given to moving these valves outside the torus and drywell. At a minimum the torus flex connectors will be replaced during the next refueling outage. These valves are outside the torus and drywell on units 1 and 2. Failure Data:

None

Retention: Persod - Lifetime: Responsibility - Document Control Supervisor 5/11 *Revision: