UPDATE REPORT - PREVIOUS REPORT DATE 5/7 48 NUCLEAR REGULATORY COMMISSION NRC FORM-366 (7-77) LICENSEE EVENT REPORT 10 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) CONTROL BLOCK: 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 3 4 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 0 BR F 22 0 LICENSEE CODE CON'T 0 5 0 0 0 2 6 0 7 0 4 2 5 8 1 8 1 8 1 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 0 1 L (6) SOURCE EVENT DESCRIPTION AND PROPABLE CONSEQUENCES (10) While operating at full power steady state, a bypass was installed on MSL high temp-0 2 erature isolation relays to control unit conditions until the ventilation system could 0 3 be returned to service or a controlled shutdown initiated and MSIV's closed per T.S. 04 note 3.2.A.1.B. A reactor operator was stationed at the main steam tunnel temperature 0 5 monitor to isolate main steam lines if temperature reached T.S. limits. There was no 0 6 danger to the health or safety of the public. Previous similar event: BFR0-50-260/ 0 81017. SYSTEM COMP CAUSE VALVE CAUSE CODE SUBCODE COMPONENT CODE SUBCODE Z (15) Z (16) A (12) ZZ 2 2 Z A (13) D (11) OCCURRENCE REVISION SEQUENTIAL REPORT REPORT NO. CODE EVENT YEAR LER/RO NO XI 0 11 REPORT 0 1 8 NUMBER COMPONENT PRIME COMP. ATTACHMENT SUBMITTED NPRD-4 FUTURE METHOD (22 HOURS FORM SUB MANUFACTURER SUPPLIER 0 0 0 L (25) 0 Y (23) N (24) (26)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Individual failed to recognize installing bypass put the unit in an | 1 0 Personnel error. LCO requiring shutdown within 24 hours. Repairs were initiated, ventilation 1 1 restored, and the bypass removed within 48 minutes. Personnel were stationed to monitor as stated above. MSIV isolation signals from main steam line high flow and 4 low pressure were operable. 80 FACILITY METHOD OF (30) DISCOVERY DESCRIPTION (32) % POWER OTHER STATUS Operator observed E (28) A (31)0 80 ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED OF RELEASE Z 33 Z 34 NA NA 80 44 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE NA 0 30 Gi 0 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER (40)NA 01 8201130279 811231 80 LOSS OF OR DAMAGE TO FACILITY (43) TYPE (42) PDR ADOCK 05000260 DESCRIPTION NA PDR 80 PUBLICITY NRC USE ONLY DESCRIPTION (45) N 44 NA 1111111 69 68 80 PHONE (205) 729-6134 Gene Holder NAME OF PREPARER

Browns Ferry Nuclear Plant

LER SUPPLEMENTAL INFORMATION

 BFRO-50- 260 /81019 R1
 Technical Specification Involved 3.2.A Table 3.2.A

 Reported Under Technical Specification 6.7.2.a.5
 * Date Due NRC NA

 Date of Occurrence 4/25/81
 Time of Occurrence 1030
 Unit 2

Identification and Description of Occurrence:

While operating at full power steady state a bypass was installed on main steam line high temperature isolation relays to maintain control of unit conditions until the ventilation system could be returned to service or a controlled shutdown initiated and MSIV's closed per T.S. note 3.2.A.1.B.

Conditions Prior to Occurrence:

Unit 1 at refueling outage.

Unit 2 at 100%.

Unit 3 at 95%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

A reactor operator was stationed at the main steam tunnel temperature monitor with instructions to isolate the main steam lines if the temperature reached T.S. Limits.

Apparent Cause of Occurrence:

Personnel error.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Repairs were made and the requirements of the applicable LCO were satisfied The individual involved was reprimanded in writing.

Failure Data:

None <u>Retention</u>: Period - Lifetime; Responsibility - Document Control Supervisor *Revision: Analame