


Mr. R. C. Haynes, Director
Office of Inspection & Enforcement, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

No. 3-81-18/3L-0

Dear Mr. Haynes:

This LER concerns the failure of a HPCI turbine steam supply valve due to a blown fuse. Applicable Technical Specification is 4.5.C.2.



LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P | A | P | B | S | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | _____ | 5
 7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CON'T
 0 1 | R | E | P | O | R | T | S | O | U | R | C | E | L | 6 | 0 | 5 | 1 | 0 | - | 0 | 1 | 2 | 7 | 8 | 7 | 1 | 1 | 2 | 4 | 8 | 1 | 8 | 1 | 2 | 2 | 4 | 8 | 1 | 9
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While undergoing surveillance testing, the HPCI turbine steam supply
 0 3 | valve (MO-3-123-14) failed to open. The HPCI system was declared
 0 4 | inoperable and surveillance testing on the backup systems was initiated
 0 5 | in accordance with Tech Spec 4.5.C.2.
 0 6 |
 0 7 |
 0 8 |

0 9 | SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
 E C 11 E 12 A 13 I N S T R U 14 X 15 Z 16
 9 10 11 12 13 14 15 16 17 18 19 20
 17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 8 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 A 18 Z 19 Z 20 Z 21 0 0 0 0 0 22 N 23 Y 24 Z 25 Z 26 9 9 9 26
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The valve was stroked full open and closed by hand and operated
 1 1 | properly. Further investigation determined a blown fuse in the valve
 1 2 | motor circuit was responsible for the failure. The fuse was replaced,
 1 3 | the surveillance test performed satisfactorily, and the HPCI system
 1 4 | declared operational.

1 5 | FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
 E 28 0 9 5 29 N/A B 31 Operator Observation
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 1 6 | ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (26)
 Z 33 Z 34 N/A N/A
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 1 7 | PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (33)
 0 0 0 37 Z 38 N/A
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 1 8 | PERSONNEL INJURIES NUMBER DESCRIPTION (41)
 0 0 0 40 N/A
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
 Z 42 N/A
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 | PUBLICITY ISSUED DESCRIPTION (45)
 N 44
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 NAME OF PREPARER M. J. Cooney PHONE (215) 841-5020
 8201150277 811224
 PDR ADDCK 05000278
 S PDR
 NRC USE ONLY
 501