NRC FORM (7-77) ~	366 U. S. NUCLEAN REQUEATION & COMMISSION
	LICENSEE EVENT REPORT
	CONTROL BLOCK:
	M N P I N 1 2 0 0 - 0 0 0 - 0 0 3 4 1 <th1< th=""> <th1< th=""> <th1< th=""></th1<></th1<></th1<>
CON'T	REPORT SOURCE L 6 0 5 0 0 0 2 8 2 7 1 2 1 0 8 1 8 0 1 15 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During routine surveillance test of Bus 16 undervoltage relays, an error in dis-
0 3	connecting test equipment resulted in blowing fuse for A-phase relays. C-phase
0 4	fuse was removed as part of test procedure. The voltage restoration and load
0 5	rejection scheme initiated, and since UV condition continued to be sensed, closed D2
06	diesel supply breaker. D2 breaker remained closed with bus deenergized until fuses
0 7	replaced and Bus 16 reenergized from its normal offsite source. No effect on
08	public health and safety. Bus 15, the redundant bus, remained fully operable.
7 8 9 0 9 7 8	SYSTEM CODE B B 10 CAUSE SUBCODE CODE SUBCODE CODE SUBCODE CODE SUBCODE CODE SUBCODE CODE SUBCODE COMPONENT CODE COMPONENT CODE SUBCOD
(Image: Nome and Security Part Nome and Security Par
A T	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
101	Fuses were replaced and normal power restored to bus. The undervoltage relay tests,
	for all four safeguard buses, will be revised to include two separate steps
12	with signoffs when disconnecting test equipment. The existing procedure
13	uses a single step to disconnect test equipment at the bus cubicle and at the logic
14	relay cabinet. Two steps will make an error of this type less likely.
	ACILITY TATUS S POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32 E 28 10 0 29 NA B 31 Surveillance test 32
	TIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY 35 2 33 2 34 10 11 A44 45 LOCATION OF RELEASE 36 NA 10 11 10 11 10 10 10 10 10 10 10 10 10
19	I DESCRIPTION NA I DESCRIPTION NA I DESCRIPTION NA
	PUBLICITY SSUED DESCRIPTION (45) NRC USE ONLY NA
8201	210 265 D M Musolf PHONE 612-330-6764

.