

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | C | R | P | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 2 | 4 | 1 | 1 | 1 | 1 | 4 | 5

0 1 | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 0 | 2 | 7 | 1 | 2 | 1 | 8 | 8 | 1 | 2 | 0 | 1 | 1 | 5 | 8 | 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
At 1300, while increasing Reactor power, an operator identified that "A" OTSG operating level was not trending up with Reactor power. This created an event contrary to having two (2) operable level indications per Steam Generator as set forth in T.S. 3.3.3.6. LT-3 was selected for ICS control and initiated maintenance. Operability was restored at 1445 on December 22, 1981. There was no effect upon the health or safety of the general public. This was the first occurrence of this type, and this is the fifth event reported under this Specification.

0 9 | C | C | 11 | E | 12 | A | 13 | I | N | S | T | R | U | 14 | T | 15 | Z | 16 | 8 | 1 | 21 | 22 | 0 | 7 | 9 | 24 | 26 | 0 | 3 | 28 | 29 | L | 30 | 0 | 32 | A | 33 | Z | 34 | Z | 35 | Z | 36 | 0 | 0 | 0 | 0 | 37 | 40 | Y | 41 | 23 | N | 42 | 24 | N | 43 | 25 | B | 0 | 4 | 5 | 44 | 47 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
The cause of this event is attributed to the failure of the level transmitter amplifier, LT-2, causing the sealed unit to become inoperative. The level transmitter amplifier was replaced, and the channel was calibrated. No further corrective action is deemed necessary.

1 5 | E | 28 | 0 | 9 | 6 | 29 | NA | 30 | A | 31 | Operator observation | 32 | Z | 33 | Z | 34 | NA | 35 | NA | 36 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 | 0 | 0 | 0 | 40 | NA | 41 | Z | 42 | NA | 43 | N | 44 | NA | 45

8201260412 820115
PDR ADDCK 05000302
S PDR

NRC USE ONLY

NAME OF PREPARER Charles S. Brown / DSM

PHONE 904/795-6486

GPO 017-926

SUPPLEMENTARY INFORMATION

Report No.: 50-302/81-079/03L-0

Facility: Crystal River Unit 3

Report Date: January 15, 1982

Occurrence Date: December 18, 1981

Identification of Occurrence:

One level transmitter amplifier for "A" Once Through Steam Generator was inoperable contrary to Technical Specification 3.3.3.6.

Conditions Prior to Occurrence:

Mode 1 (96%)

Description of Occurrence:

At 1300 while increasing Reactor power, an operator identified that "A" Once Through Steam Generator level was not trending up with Reactor power. Level transmitter three (3) was selected for integrated system control, and maintenance was initiated. Operability was restored at 1445 on December 22, 1981.

Designation of Apparent Cause:

The cause of this event is attributed to the failure of the level transmitter amplifier causing the sealed unit to become inoperative.

Analysis of Occurrence:

There was no effect upon the health or safety of the general public.

Corrective Action:

The level transmitter amplifier was replaced and the channel was calibrated. No further corrective action is deemed necessary.

Failure Data:

This was the first occurrence of this type and this is the fifth event reported under this Specification.

/rc