

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	M	I	D	C	C	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
LICENSEE CODE														LICENSE NUMBER						LICENSE TYPE					CAT 58		

01	L	6	0	5	0	0	0	3	1	5	7	1	2	2	9	8	1	3	0	1	1	9	8	2	2
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
CON'T		DOCKET NUMBER												EVENT DATE					REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | DURING SURVEILLANCE TEST PER T.S. 4.4.6.2.1B, UNIDENTIFIED RCS LEAKAGE WAS

03 | DETERMINE TO BE 1.08 GPM, WHICH EXCEEDED THE 1 GPM LIMIT OF T.S. 3.4.6.2 B.

04 | THE ACTION REQUIREMENTS WERE MET. THE UNIT WAS SHUTDOWN. THE RCS WAS COOLED,

05 | DEPRESSURIZED AND DRAINED TO HALF LOOP. CONTAINMENT INSPECTION REVEALED A

06 | PACKING LEAK ON THE PRESSURIZER SPRAY CONTROL VALVE, NRV-164. THIS WAS THE

07 | FIRST OCCURRENCE OF THIS TYPE. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

03	C	B	11	E	12	B	13	V	A	L	V	E	X	14	F	15	D	16																									
7	8	9	10	11	12	13	14	15	16	17	18	19	20																														
SYSTEM CODE			CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE																												
03	17	8	1	0	6	2	0	3	L	0	0	0																															
7	8	9	10	11	12	13	14	15	16	17	18	19																															
LER NO REPORT NUMBER			EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.																																
ACTION TAKEN			FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																										
A			Z		A		A		0		2		8		0		N		Y		N		C		6		3		5														
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | THE BELLOWS SEAL, PART NO. 137522, OF THE 4 INCH COPES WELCAN GLOBE VALVE FAILED

11 | ALLOWING RCS PRESSURE TO BE EXERTED ON THE PACKING. THE PACKING LEAKED. VALVE

12 | REPAIRS INCLUDED REPLACEMENT OF THE TRIM ASSEMBLY, CAGE SPACER, AND GASKETS.

13 | THE VALVE WAS REPACKED AND FUNCTIONALLY TESTED.

15	E	28	1	0	0	29	NA	B	31	SURVEILLANCE TEST	32			
7	8	9	10	11	12	13	14	15	16	17	18			
FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
PERSONNEL EXPOSURES			PERSONNEL INJURIES			LOSS OF OR DAMAGE TO FACILITY			PUBLICITY			ISSUED DESCRIPTION		
0			0			0			Z			NA		
0			0			0			Z			NA		
Z			NA			NA			NA			NA		
Z			NA			NA			NA			NA		
Z			NA			NA			NA			NA		

8201270548 820119
PDR ADOCK 05000315
S PDR

NRC USE ONLY