

CONTROL BLOCK: 

--	--	--	--	--	--

 (1)

7	0	1	9	A	L	B	R	F	1	14	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	57	CAT	58	
				LICENSEE CODE							LICENSE NUMBER														LICENSE TYPE								

0	1	REPORT SOURCE		L	6	0	5	0	0	0	2	5	9	7	1	2	1	1	8	1	H	0	1	0	8	8	2	U		
7	8			60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

0 2 During normal operation, HPCI suppression chamber high level switches were discovered  
0 3 to be set 8 inches above normal level. T.S. Table 3.2.B limit is  $\leq$  7 inches  
0 4 above normal level. There was no effect on the health or safety of the public  
0 5 in that HPCI was available in the manual mode and other ECCS were operable. There  
0 6 were no previous similar events.

SYSTEM CODE      CAUSE CODE      CAUSE SUBCODE      COMPONENT CODE      COMP SUBCODE      VALVE SUBCODE  
 C   B   (11)      A   (12)      X   (13)      I   N   S   T   R   U   (14)      S   (15)      Z   (16)

(17) LER RD REPORT NUMBER

EVENT YEAR			SEQUENTIAL REPORT NO.			OCCURRENCE CODE			REPORT TYPE		REVISION NO.
[8]	[1]	[—]	[0]	[8]	[5]	[/]	[0]	[3]	[L]	[—]	[0]
21	22	23	24	25	26	27	28	29	30	31	32

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
E	18	F	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	L	25	R	2	9	0
32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53

110 A T.S. change revised normal water levels in T.S. 3.7.A down one inch. This was  
111 not refelcted in T.S. Table 3.2.B. LS-73-57A and B were physically lowered  
112 1-3/4 inch plus or minus 1/4 inch to comply with T.S. limits of Table 3.2.B.

FACILITY STATUS: 1 0 E 28  
% POWER: 0 9 9 29  
OTHER STATUS: NA 30  
METHOD OF DISCOVERY: B 31  
DISCOVERY DESCRIPTION: Surveillance Instruction Review 32

ACTIVITY		CONTENT		RELEASED		OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	2	13	3	34	NA				NA	
7	8	9	10	11	12	44				45	

PERSONNEL EXPOSURE		NUMBER		TYPE		DESCRIPTION	
1	2	0	0	0	39	Z	38
		NA					

PERSONNEL INJURED		NUMBER		DESCRIPTION	
1	2	0	0	0	NA

8201280347 820108

COPIES OF OR DAMAGE TO FACILITY (4.1)  
TYPE DESCRIPTION NA  
S PDR ADCK 05000259 PDR

PUBLICATION		ISSUED		DESCRIPTION		NRC USE ONLY													
2	11	N	44	NA															
7	8	9	10																

NRC USE ONLY

Gene Holder

PHONE: (205) 729-6134

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81085 Technical Specification Involved Table 3.2.B  
Reported Under Technical Specification 6.7.2.b(2) \* Date Due NRC 1/10/82  
Date of Occurrence 12/11/81 Time of Occurrence 1400 Unit 1

Identification and Description of Occurrence:

HPCI suppression chamber high level switches were discovered to be set 8 inches above normal level. T.S. Table 3.2.B limit is - 7 inches above normal level.

Conditions Prior to Occurrence:

Unit 1 at 99%

Unit 2 at 100%.

Unit 3 in refueling outage.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Performed operability SI's on redundant systems.

Apparent Cause of Occurrence:

T.S. change revised normal water levels in T.S. 3.7.A down one inch. This was not reflected in table 3.2.B.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

LS-73-57A & B were physically lowered 1-3/4 inch plus or minus 1/4 inch to within T.S. limits of table 3.2.B.

Failure Data:

None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: John A. [Signature]