

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | V | A | S | P | S | 1 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5

01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 0 | 7 | 0 | 1 | 1 | 9 | 8 | 2 | E | D | 2 | 0 | 8 | 8 | 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | With the unit at 100%, during the performance of PT 26.1, it was found that the
03 | alarm setpoint for rad. monitor, RM-GW-102, had exceeded the allowable limit
04 | stated in Tech. Spec. 3.7, table 3.7-5. This event is reportable per Tech. Spec.
05 | 6.6.2.b.(4). Since the activity levels remained within the allowable limits, the
06 | health and safety of the public were not affected.

09 | M | B | 11 | E | 12 | E | 13 | I | N | S | T | R | U | 14 | Y | 15 | Z | 16

17 | 8 | 2 | 0 | 0 | 6 | 0 | 3 | 1 | 0

18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 0 | 0 | Y | 23 | N | 24 | A | 25 | V | 1 | 1 | 1 | 5 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of this event was instrument drift. The instrument technicians were
11 | present at the time the PT was performed and were immediately available to
12 | recalibrate the monitor.

15 | E | 28 | 1 | 0 | 0 | 29 | N/A | B | 31 | Operator Observation 32

16 | Z | 33 | Z | 34 | N/A | N/A | 36

17 | 0 | 0 | 0 | 37 | Z | 38 | N/A | 39

18 | 0 | 0 | 0 | 40 | N/A | 41

19 | Z | 42 | N/A | 43

20 | N | 44 | N/A | 45

ATTACHMENT 1
SUNRISE POWER STATION, UNIT NO.1
DOCKET NO: 50-280
REPORT NO: 82-006/03L-0
EVENT DATE: 1-19-82

TITLE OF EVENT: RM-GW-102 HIGH SETPOINT

1. DESCRIPTION OF EVENT:

On 1-19-82 with the unit at 100% power, while performing PT-26.1, Radiation Monitoring Equipment Check, the alarm setpoint for gaseous waste monitor, RM-GW-102, was found to be higher than allowed. The alarm setpoint of the instrument was 4×10^5 cps while it should have been 3.57×10^5 cps. This event is contrary to Technical Specification 3.7, Table 3.7-5 and is reportable per Technical Specification 6.6.2.b.(4).

2. PROBABLE CONSEQUENCES OF OCCURRENCE:

The activity level in the gaseous waste system remained within allowable limits. Actual activity level as recorded on radiation monitor recorder, RR-175, shows no increase in activity during the event. Therefore, the automatic functions actuated by the radiation monitor were not required and the health and safety of the public were not affected.

3. CAUSE OF THE EVENT:

The cause of this event was instrument drift.

4. IMMEDIATE CORRECTIVE ACTIONS:

Instrument technicians were present at the time the periodic test was performed and were available to recalibrate the monitor's setpoint to within the specification. Since the instrument was immediately recalibrated and the activity level was acceptable, it was not deemed necessary to initiate the abnormal procedure.

5. SUBSEQUENT CORRECTIVE ACTIONS:

None were necessary.

6. FUTURE CORRECTIVE ACTIONS:

None are necessary.

7. GENERIC IMPLICATIONS:

None.