

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT
/0/1/ REPORT SOURCE /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/1/1/6/8/2/ (8) /0/2/0/9/8/2/ (9)
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On January 16, 1982, with Unit No.1 at 100% power, the 1J Emergency Diesel Gener-
/0/3/ / ator access door would not latch. A fire watch was posted immediately and the
/0/4/ / latch plate was repositioned; therefore, the health and safety of the general
/0/5/ / public were not affected. This event is contrary to the LCO for T.S. 3.7.15 and
/0/6/ / reportable pursuant to T.S. 6.9.1.9.b.
/0/7/ /
/0/8/ /

SYSTEM CAUSE CAUSE COMP. VALVE
CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE

/0/9/ /A/B/ (11) /E/ (12) /B/ (13) /X/X/X/X/X/X/ (14) /Z/ (15) /Z/ (16)
LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION
REPORT NO. TYPE NO.
(17) NUMBER /8/2/ /-/ /0/0/4/ / \ / /0/3/ /L/ /-/ /0/

ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
/E/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /Y/(23) /N/(24) /A/(25) /C/1/7/5/(26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The latch cover plate became loose, preventing the door from latching properly.
/1/1/ / The latch plate was repositioned to allow the door to latch normally. The latch
/1/2/ / was subsequently repaired by the Mechanical Maintenance Department.
/1/3/ /
/1/4/ /

FACILITY METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
STATUS %POWER OTHER STATUS (30) DISCOVERY
/1/5/ /E/ (28) /1/0/0/ (29) / NA / /A/ (31) / Operator Observation /

ACTIVITY CONTENT LOCATION OF RELEASE (36)
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
/1/6/ /Z/ (33) /Z/ (34) / NA / / NA /

PERSONNEL EXPOSURES DESCRIPTION (39)
NUMBER TYPE
/1/7/ /0/0/0/ (37) /Z/ (38) / NA /

PERSONNEL INJURIES DESCRIPTION (41)
NUMBER
/1/8/ /0/0/0/ (40) / NA /

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
/1/9/ /Z/ (42) / NA /

PUBLICITY
ISSUED DESCRIPTION (45) 8202220293 820209 NRC USE ONLY
/2/0/ /N/ (44) / NA / PDR ADOCK 05000338 S PDR / / / / / / / / / / / / /

NAME OF PREPARER W. R. CARTWRIGHT PHONE (703) 894-5151

Virginia Electric and Power Company
North Anna Power Station, Unit No. 1
Docket No. 50-338
Report No. LER 82-004/03L-0

Attachment: Page 1 of 1

Description of Event

On January 16, 1982, with Unit No. 1 at 100% power, the fire door between the Turbine Building and the 1J Emergency Diesel Generator Room would not latch.

Probable Consequences of Occurrence

A fire watch was posted immediately and the latch plate was repositioned to allow normal operability; therefore, the health and safety of the general public were not affected.

Cause of Event

The latch cover plate was loose and restricted normal closure and latching of the 1J Emergency Diesel Generator Door.

Immediate Corrective Action

A fire watch was posted immediately and the latch cover was repositioned. The latch was permanently repaired within two days. The temporary repair allowed the door to remain operable until the permanent repair was completed.

Scheduled Corrective Action

No further corrective action is scheduled.

Actions Taken to Prevent Recurrence

No further action is required.

Generic Implications

There are no generic implications associated with this event.