LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	N C B E P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
O 1 8	REPORT L 6 0 5 0 - 0 3 2 5 7 0 1 1 6 8 2 8 0 2 1 1 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During plant operation while performing Control Rod Operability Check, PT 14.1, it
0 3	was discovered that control rod 14-11 had a "Rod Drift" annunciation and lack of RTGB
0 4	position indication at rod positions "34" and "35". Actual rod position was verified
0 5	by alternate methods in accordance with technical specifications. This event did not
0 6	affect the health and safety of the public.
0 7	Technical Specifications 3.1.3.7, 6.9.1.9b
0 8	9
0 9	SYSTEM CODE CODE SUBCODE SUBCO
	TAKEN ACTION FUTURE TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORMSUB. SUPPLIER MANUFACTURER X 18 X 19 Z 20 Z 21 21 22 23 37 40 41 23 42 43 43 43 45 47 47 47 47 47 47 47
1 0	Initial troubleshooting has determined the most probable cause of the indicated
1 1	problem is defective rod position indication reed switches. This problem will be
1 2	fully investigated and corrected during a future outage. This type of failure does
1 3	not constitute a safety hazard and is expected on an occasional basis; therefore, no
1 4	design modifications are planned.
1 5	FACILITY STATUS NO POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32 NA B 31 NA 80
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O 37 Z 38 NA PERSONNEL INJURIES NA 80
1 8	NA NA 80
1 9	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA
7 8	PUBLICITY ISSUED DESCRIPTION 45 PDR ADDCK 05000325 S PDR ADDCK 05000325 S PDR NA
7 8	M. J. Pastva, Jr. (919) 457-9521