

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

N J O C P 1 7 0 0 - 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 1 4 5

L 0 5 0 0 0 2 1 9 7 0 1 2 6 8 2 0 2 2 5 8 2 0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During surveillance testing the Main Steam Line High Flow Sensor RE-22H tripped at a value greater than that given in the Technical Specifications. The safety significance is considered minimal because the redundant sensor RE-22D in the same circuit would have activated within the desired limit.

SYSTEM CODE: C D (11)
 CAUSE CODE: X (12)
 CAUSE SUBCODE: Z (13)
 COMPONENT CODE: I N S T R U (14)
 COMP. SUBCODE: E (15)
 VALVE SUBCODE: Z (16)

EVENT YEAR: 8 2 (17)
 SEQUENTIAL REPORT NO.: 0 0 7 (18)
 OCCURRENCE CODE: 0 3 (19)
 REPORT TYPE: L (20)
 REVISION NO.: 0 (21)

ACTION TAKEN: E (22)
 EFFECT ON PLANT: Z (23)
 SHUTDOWN METHOD: Z (24)
 HOURS: 0 0 0 0 (25)
 ATTACHMENT SUBMITTED: Y (26)
 NPRM FORM SUB.: Y (27)
 PRIME COMP. SUPPLIER: L (28)
 COMPONENT MANUFACTURER: I 2 0 4 (29)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause was attributed to instrument repeatability and drift. Sensor RE-22H was operating slightly outside of its design accuracy. The sensor was reset to trip within the required limit. The "As Left" setpoints were lowered to account for instrument drift.

FACILITY STATUS: H (30)
 % POWER: 0 0 0 (31)
 OTHER STATUS: NA (32)
 METHOD OF DISCOVERY: B (33) Surveillance Test (34)

ACTIVITY CONTENT: Z (35)
 AMOUNT OF ACTIVITY: NA (36)
 LOCATION OF RELEASE: NA (37)

PERSONNEL EXPOSURES: NUMBER 0 0 0 (38) TYPE Z (39) DESCRIPTION NA (40)

PERSONNEL INJURIES: NUMBER 0 0 0 (41) DESCRIPTION NA (42)

LOSS OF OR DAMAGE TO PROPERTY: TYPE Z (43) DESCRIPTION NA (44)
 8203090231 820225
 PDR ADOCK 05000219
 S PDR

PUBLICITY ISSUED: N (45) DESCRIPTION NA (46)
 NAME OF REPORTER: Hamid Pirooz
 NRC USE ONLY
 PHONE: (609) 971-4418