

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36
		LICENSEE CODE							LICENSE NUMBER										LICENSE TYPE					CAT 58					

0	1	L	6	0	5	0	0	0	2	7	2	7	0	2	0	1	8	2	8	0	3	0	3	8	2	9			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36
		REPORT SOURCE		DOCKET NUMBER								EVENT DATE						REPORT DATE											

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0915 hours, February 1, 1982, a temporary hose connection from No. 1 Unit Spent
 0 3 | Fuel Pool to No. 2 Unit Spent Fuel Pool Heat Exchanger developed a leak on the 84'
 0 4 | Elevation, No. 1 Auxiliary Building, at the hose connection. At 0927 hours the leak
 0 5 | was isolated. At 0935 hours the Spent Fuel Pit level was verified to be greater
 0 6 | than 23 feet above the top of the fuel assemblies. The volume of the spill was
 0 7 | estimated at 23,000 gallons. At 1600 hours an unusual event was declared and the
 0 8 | Emergency Procedure EPI-1 was complied with.

0	9	F	C	11	E	12	X	13	X	X	X	X	X	X	X	14	X	15	Z	16	17	8	2	18	0	1	0	19	0	20	0	21	0	0	0	0	22	Y	23	N	24	N	25	Z	9	9	9	9	26				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE		LER-RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NC		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The temporary hose leaked at the hose connection. At 1230 hours, the cooling flow
 1 1 | for No. 1 Spent Fuel Pool was returned to the No. 1 Spent Fuel Pool Heat Exchanger.
 1 2 | The temporary hose to No. 2 Spent Fuel Pool Heat Exchanger was disconnected. Later,
 1 3 | it was reconnected utilizing double hose clamps and calculated torque specifi-
 1 4 | cations.

1	5	H	28	0	0	0	29	N/A	30	A	31	Water Leak	32					
7	8	9	10	11	12	13	14	15	16	17	18	19	20					
		FACILITY STATUS		% POWER				OTHER STATUS			METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	6	Z	33	Z	34	N/A	35	N/A	36	N/A	37	N/A	38					
7	8	9	10	11	12	13	14	15	16	17	18	19	20					
		ACTIVITY CONTENT RELEASED		AMOUNT OF ACTIVITY				LOCATION OF RELEASE										
1	7	0	0	0	37	Z	38	N/A	39	N/A	40	N/A	41					
7	8	9	10	11	12	13	14	15	16	17	18	19	20					
		PERSONNEL EXPOSURES NUMBER		TYPE		DESCRIPTION												
1	8	0	0	0	40	N/A	41	N/A	42	N/A	43	N/A	44					
7	8	9	10	11	12	13	14	15	16	17	18	19	20					
		PERSONNEL INJURIES NUMBER		DESCRIPTION														
1	9	Z	42	N/A	43	N/A	44	N/A	45	N/A	46	N/A	47					
7	8	9	10	11	12	13	14	15	16	17	18	19	20					
		LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION														
2	0	N	44	N/A	45	N/A	46	N/A	47	N/A	48	N/A	49					
7	8	9	10	11	12	13	14	15	16	17	18	19	20					
		PUBLICITY ISSUED		DESCRIPTION						NRC USE ONLY								

8203160379 820303
 PDR ADOCK 05000272
 S PDR

ckey _____

PHONE: 609-935-0998