

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | S | L | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

CONT  
0 1 | R | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 5 | 7 | 0 | 2 | 0 | 4 | 8 | 2 | 8 | 0 | 3 | 0 | 8 | 8 | 2 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
0 2 | On 2/4/82 and 2/14/82 2 out of 3 control room air conditioning units were |  
0 3 | out of service simultaneously. The plant was at normal full power oper- |  
0 4 | ation. During this time the third control room air conditioner was contin- |  
0 5 | uously available. On 2/4/82 two units were out of service for 33 hours and |  
0 6 | on 2/14/82 two units were out for 19 hours. Both periods were significantly |  
0 7 | less than the 7 days allowed by Tech. Spec. 3.7.7.1. The health and safety |  
0 8 | of the public were not endangered by this event. See LER# 76-16. |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

0 9 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP SUBCODE | VALVE SUBCODE  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
A A E B X X X X X X X X X X X Z  
LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.  
17 21 22 23 24 25 26 27 28 29 30 31 32  
8 2 - 0 0 5 / 0 3 L - 0  
ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRO-4 FORM SUB. | PRIME CORP. SUPPLIER | COMPONENT MANUFACTURER  
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
B Z Z Z 0 0 0 0 N N A Z 9 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 0 | On 2/4/82, control room air conditioner HVA-3B was found to have a stuck |  
1 1 | damper and HVA-3C's damper control linkage was found to be broken. Both |  
1 2 | units were repaired and returned to service. On 2/14/82 HVA-3C was found |  
1 3 | to have a stuck damper and HVA-3B had a faulty unloading valve. Both units |  
1 4 | were repaired and returned to service. |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 5 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
E 0 9 8 NA A OPERATOR OBSERVATION

1 6 | ACTIVITY RELEASED | CONTENT OF RELEASE | AMOUNT OF ACTIVITY | LOCATION OF RELEASE  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
Z NA NA NA

1 7 | PERSONNEL EXPOSURES NUMBER | TYPE | DESCRIPTION  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
0 0 0 Z NA

1 8 | PERSONNEL INJURIES NUMBER | DESCRIPTION  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
0 0 0 NA

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | DESCRIPTION  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
Z NA

2 0 | PUBLICITY ISSUED | DESCRIPTION | NRC USE ONLY  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
N NA

NAME OF PREPARER P. L. Pace PHONE (305) 552-3654

8203170567 820308  
PDR ADOCK 05000335  
S PDR