

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	3	1	7	0	2	2	0	8	2	9	0	3	1	1	8	2	9		
50	61	DOCKET NUMBER										58	59	EVENT DATE					74	75	REPORT DATE					80

0 2 During normal operation, snubber GBB-3-SS-235 on the "B" RHR system was
0 3 removed from service for testing. The "B" RHR system was declared inoper
0 4 able while this snubber was out of service. With the "B" RHR system inop
0 5 erable, the "B" containment spray sys. was also effectively made inop. D
0 6 ue to the "A" RHR (LPCI) sys. having previously been declared inop see (

0 7 RO 82-014). A 24 hour LCO was entered per T.S. 3.5.A.6. This event was f
0 8 irst classified a 30 day RO but was reevaluated as a 14 day RO on 3/1/82.

7 8

SYSTEM CODE 9 10 (11)

CAUSE CODE 11 (12)

CAUSE SUBCODE 12 (13)

COMPONENT CODE 13 14

COMP. SUBCODE 15 (16)

VALVE SUBCODE 17

SEQUENTIAL REPORT NO. 18 19 20

OCCURRENCE CODE 21 22

REPORT TYPE 23 (24)

REVISION NO. 25

(17) LER/RO REPORT NUMBER 26 27

EVENT YEAR 28 29

ACTION TAKEN 30 31

FUTURE ACTION 32 33

EFFECT ON PLANT 34 35

SHUTDOWN METHOD 36 37

HOURS 38 39 40

ATTACHMENT SUBMITTED 41 (42)

NPRO-4 FORM SUB 43 44

PRIME COMP. SUPPLIER 45 46

COMPONENT MANUFACTURER 47 48

1 0 The snubber was removed for testing after the pipe clamp to which is att
1 1 ached was found rotated approx. 30 degrees from its proper position and
1 2 the snubber extension bent slightly. The pipe clamp was repositioned and
1 3 secured, the extension piece straightened, and the snubber replaced with
1 4 a spare. The original snubber was tested with satisfactory results.

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	0	8	6	N/A	C	31	Special Inspection					
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	6	Z	Z	N/A		N/A								
PERSONNEL EXPOSURES			PERSONNEL INJURIES			LOSS OF OR DAMAGE TO FACILITY								
NUMBER			NUMBER			TYPE			DESCRIPTION					
1	7	0	0	0	0	0	0	0	37	Z	38	N/A		
TYPE			DESCRIPTION			TYPE			DESCRIPTION					
1	4	0	0	0	0	0	0	0	40	N/A				
TYPE			DESCRIPTION			TYPE			DESCRIPTION					
1	3	Z	N/A					42	N/A					

NRC USE ONLY

NAME OF PREPARER U. van Sickle

PHONE: 319-851-5611

DUANE ARNOLD ENERGY CENTER

Iowa Electric Light and Power Company

Licensee Event Report - Supplemental Data

Docket No. 050-0331

Licensee Event Report Date: 3-11-82

Reportable Occurrence No: 82-013

Event Description:

During normal operation, snubber GBB-3-SS-235 on the "B" RHR system was removed from service for testing. The "B" RHR system was declared inoperable while this snubber was out of service. With the "B" RHR system inoperable, the "B" containment spray system was also effectively made inoperable. Due to the "A" RHR (LPCI) system having previously been declared inoperable (see RO 82-014), a 24 hour LCO was entered per Technical Specification 3.5.A.6. This event was initially classified as a 30 Day Reportable Occurrence but was reevaluated as a 14 Day Reportable Occurrence on March 1, 1982.

Cause Description:

The snubber was removed for testing after the pipe clamp to which it is attached was found rotated approximately 30 degrees from its proper position and the snubber extension was found bent slightly. The cause for these two problems is unknown. These problems in themselves did not effect the system operability. The snubber was removed to verify that it was operable. The snubber is a Bergan Patterson Model HSSA-10 hydraulic snubber.

Corrective Action:

The pipe clamp was repositioned and secured, the extension piece was straightened, and the snubber replaced with a like-for-like spare. The snubber was out of service for approximately 4 hours. The original snubber was tested with satisfactory results.