



EDISON PLAZA  
300 MADISON AVENUE  
TOLEDO, OHIO 43652-0001

May 3, 1990

Log No.: BB90-00702  
NP33-90-007

Docket No. 50-346  
License No. NPF-3

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Gentlemen:

LER 90-006  
Davis-Besse Nuclear Power Station, Unit No. 1  
Date of Occurrence - April 3, 1990

Enclosed please find Licensee Event Report 90-006 which is being written to provide 30 days notification of the subject occurrence. This report is being submitted in accordance with 10CFR50.73(a)(2)(iv).

Yours truly,

A handwritten signature in cursive script that reads 'Louis F. Storz'.

Louis F. Storz  
Plant Manager  
Davis-Besse Nuclear Power Station

LFS/plf

Enclosure

cc: Mr. A. Bert Davis  
Regional Administrator  
USNRC Region III

Mr. Paul Byron  
DB-1 NRC Sr. Resident Inspector

9005080090 900503  
PDR ADOCK 05000346  
S PDC

IE22  
11

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Davis-Besse Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 3 4 6 1	PAGE (3) 1 OF 3
---	--	--------------------

TITLE (4)  
Inadvertent SFAS Actuation While Defueled When Breaker Switch HAAE2 Was Bumped Open

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
04	03	90	90	006	000	05	03	90			05000
											05000

OPERATING MODE (9) D	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
	20.602(b)	<input type="checkbox"/>	20.608(e)	<input checked="" type="checkbox"/>	60.73(a)(2)(iv)	<input type="checkbox"/>	73.71(b)	<input type="checkbox"/>		
	20.603(a)(1)(i)	<input type="checkbox"/>	60.36(a)(1)	<input type="checkbox"/>	60.73(a)(2)(v)	<input type="checkbox"/>	73.71(e)	<input type="checkbox"/>		
	20.608(a)(1)(iii)	<input type="checkbox"/>	60.36(a)(2)	<input type="checkbox"/>	60.73(a)(2)(vii)	<input type="checkbox"/>	OTHER (Specify in Abstract below and in Text, NRC Form 366A)			
	20.608(a)(1)(iii)	<input type="checkbox"/>	60.73(a)(2)(ii)	<input type="checkbox"/>	60.73(a)(2)(viii)(A)	<input type="checkbox"/>				
	20.608(a)(1)(iv)	<input type="checkbox"/>	60.73(a)(2)(ii)	<input type="checkbox"/>	60.73(a)(2)(viii)(B)	<input type="checkbox"/>				
20.608(a)(1)(v)	<input type="checkbox"/>	60.73(a)(2)(ii)	<input type="checkbox"/>	60.73(a)(2)(ix)	<input type="checkbox"/>					

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
Jan C. Stotz, Engineer - Maintenance Planning	4 1 9 3 2 1 - 7 5 4 4

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On April 3, 1990, at 0905 hours, with the reactor defueled, the station experienced a Safety Features Actuation System (SFAS) Level 1 through 5 actuation. It was initiated by an accidental bumping of a breaker switch. When the switch opened, it de-energized a bus and resulted in the loss of power to SFAS Channels 1 and 3. This caused a full SFAS logic actuation. Being defueled, most Engineered Safety Feature Systems had been disabled to prevent inadvertent actuation. As a result of the automatic opening of one of the isolation valves, the boundary of an ongoing hydrotest changed, and an open drain line was exposed to 500 psig. The clothing of one worker was contaminated. Operations management held meetings with all craft personnel to discuss the importance of being careful around plant equipment and the consequences of this event.

The NRC was notified via the ENS under 10CFR50.72(b)(2)(ii). This is being reported as an LER under 10CFR50.73(a)(2)(iv) as an automatic actuation of ESF equipment.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Davis-Besse Unit No. 1	DOCKET NUMBER (2)  0 5 0 0 0 3 4 6	LER NUMBER (5)			PAGE (3)	
		YEAR 9 0	SEQUENTIAL NUMBER 0 0 6	REVISION NUMBER 0 1 0	0 2	OF 0 3

TEXT (If more space is req. use additional NRC Form 388A w/ (17))

Description of Occurrence:

On April 3, 1990, at 0905 hours, with the reactor defueled, the station experienced an inadvertent Safety Features Actuation System (SFAS-JE) Levels 1 through 5 actuation. Being defueled, most Engineered Safety Features (ESF) Systems had been disabled to prevent inadvertent actuations. Equipment that did actuate included the ventilation dampers, containment isolation valves, and Emergency Diesel Generator (EDG) 1-2. One of the isolation valves that actuated was HP2A. This changed the boundary of an ongoing hydrotest, and an open drain line was exposed to 500 psig. The clothing of one worker was contaminated.

This is being reported under 10CFR50.73(a)(2)(iv) as an automatic actuation of ESF equipment. The NRC was notified via the ENS under 10CFR50.74(b)(2)(ii).

Apparent Cause of Occurrence:

This event initiated when a contract electrician made accidental contact with breaker switch HAAE2 in the #2 High Voltage Switchgear Room. The switch opened and de-energized bus E2. This caused a loss of power to instrument bus YAR. Due to outage maintenance and modifications, the station was in an abnormal but allowable bus lineup with both Y1 and Y3, 120 VAC Essential Buses, powered by YAR. When YAR de-energized, the loss of power to Y1 and Y3 caused a loss of power to SFAS Channels 1 and 3, respectively. This satisfied the necessary logic for a full SFAS actuation.

Contributing to this event is the design of the SFAS logic which prevents bypassing or de-energizing without causing an output signal which fails equipment to their safety position. Much of the equipment was de-energized and secured when the plant reached modes that no longer required the equipment. However, some equipment was still in use such as ventilation into containment and station air. In some cases, a system had been disabled by opening the breaker for the pump, but associated valves were not disabled because the system would not be able to function with the pump already disabled.

Analysis of Occurrence:

The Technical Specifications do not require SFAS to be operable with the reactor defueled. There is no credible design basis accident in this configuration. There is no safety significance to this event.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Davis-Besse Unit No. 1	DOCKET NUMBER (2)  0   5   0   0   0   3   4   6	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		90	006	0	003	OF	03

TEXT IN THIS SPACE IS REQUIRED, USE ADDITIONAL NRC Form 266A's (17)

Corrective Actions to Prevent Recurrence:

Power was restored to bus E2 at 0930 hours. By 0935 hours, Y1 and Y3 were re-energized. By 1115 hours, all actuated equipment was restored to its pre-actuated status.

Operations management held information meetings with all craft to discuss the importance of being careful around plant equipment and the consequences of this event.

Failure Data:

The previous inadvertent SFAS actuation was reported on LER 89-017. That event was caused by a failed relay in one SFAS Channel that was not detected prior to testing a second channel. The next previous event was reported in LER 88-012 in which two containment radiation monitors were tripped during a refueling outage when personnel passed too close to them with radioactive waste material being removed from containment. Neither of these events had causes related to this event.

REPORT NO.: NP33-90-007

PCAO NO.: 90-0275 & 90-0277