Gira Nuclear

18 **-** 81

Ļ

a () /

10 14

.

Ċ,

900515 0500021

05220069

S PDR

GPU Nuclear Corporation

Post Office Box 388 Route 9 South Forked River, New Jersey 08731-0388 609 971-4000 Writer's Direct Dial Number:

May 15, 1990

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Dear Sir:

Subject: Oyster Creek Nuclear Generating Station Docket No. 50-219 Licensee Event Report Revision

This letter forwards one (1) copy of Licensee Event Report (LER) No. 89-025, Rev. 1. The analysis of Occurrence and Safety Assessment section has been revised to clarify the conclusions of the Safety Evaluation which was performed for this event. A bar has been placed in the right side margin indicate the revised wording.

Very truly yours,

E.E. Fitzpåtrick Vice President and Director Oyster Creek

EEF/JJR:jc (ler/Covltrs:jc) Enclosure

cc: Mr. Thomas Martin, Administrator Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Mr. Alexander W. Dromerick, Project Manager U.S. Nuclear Regulatory Commission Washington, DC 20555

NRC Resident Inspector Oyster Creek Nuclear Generating Station Forked River, NJ 08731

EZZ

GPU Nuclear Corporation is a subsidiary of General Public Utilities Corporation

NAC Perm 20 2431		uci	ENSEE EVEN	T REPORT	(LER)		CLEAR REGULA PROVED ONE N KPIREE 6/31/06	FOR Y CONSMISSION IO. 3180-0104
		*****						PAGE 13
0y	ster Creek	Unit 1				0 15 10 10	01211	9 1 OFD 14
Inadvertent,	Simultaneous	Mov en en	t of Two C	Control Ro				
EVENT DATE (S)	YEAR SEQUENTIA	and the second second second second second	NEPORT DATE	IT YEAR	OTHER P	ACILITIES INVOL	DOCKET NUMBE	(A(S)
MONTH DAY YEAR	YEAR HUNGER	NUMBER	NONTH DAY				0 15 10 10	
.1			- 1- 1-1-1-	1				
1 2 1 6 8 9	8 9 0 2 5		and a second sec	0		MANUAL CONTRACTOR	0 15 10 10	
OPERATING MODE (9) POWER LEVEL -	20.402(b) 20.405(a)(1)(i) 20.405(a)(1)(ii) 20.405(a)(1)(iii) 20.405(a)(1)(iii) 20.405(a)(1)(iii) 20.405(a)(1)(iii)		20.465(a) 60.25(a)(1) 60.35(a)(2) 90.73(a)(2)(1) 60.73(a)(2)(3) 90.73(a)(2)(1)		80.73(a)(2)(iv) 80.73(a)(2)(v) 80.73(a)(2)(vi) 80.73(a)(2)(vii)(0) 80.73(a)(2)(vii)(0) 80.73(a)(2)(vii)		73,7161 73,7160 73,7160	aacilly in Abstract in Taxt, NRC Form
NAME		LK	CENSEE CONTACT P				TELEPHONE NUN	
Roger Cayl	ey					AREA CODE	9 ⁷ ¹ Γ	1414 16 11
	and the survey of the survey o	T	LACH COMPONENT	AILURE DESCRIB	ED IN THIS REPORT			
CAUSE SYSTEM COMPO	TURER	TO NPROS		CAUSE SYSTEM	COMPONENT	TURER	TO NPROS	•
					┿╾┶╼┶╼┥			•
						111		
	BUPPLEM	INTAL REPORT	IXPECTED (14)			EXPECTEL		H DAY YEAR
TES III ver. comprete EXI	CTAD SUBMISSION DAT		NO			DATE (15	, 01	1 1 9 1
increa incor proper push h not i initia Correa The s Evaluation with the affect quest	cember 16, 19 asing power w rect control r rod. Due to buttons, two co mmediately re ated a rod w ctive actions afety signifi- ation conclud the reactor v ted transien con. A supple ansients with	with cont rod, re to the ma control r ealize th ithdrawal were ta icance of led that essel he ts and emental L	trol rods. Dalized the inner in w ods were s hat two rol. Both s ken immedi this even the simul- ad in place does not ER will be	The CRO e error hich the simultaneous ods were selected of ately to ent is con- taneous mo- taneous mo	D inadvert and select CRO operatously select simultaneo control ro terminate msidered m ovement of in the des tute an u d when an o	ently set ted the red the r ted. Th usly set ds began rod move inimal. two con sign basi unreviewe ongoing e	lected a adjacent od selec e CRO di ected an to move ment. A Safet trol rod s for th d safet evaluatio	n t d d s s e y

NRC Ferm 300

.

1

	LICENSEE EVENT	REPORT (LER) TEXT CONTINU	OITAL	N		APPROVED O EXPIRES 8/3	ME NO. 3150-	0104		
PACILITY NAME (1)		DOCKET NUMBER (2)		L			PAGE (3)			
			-	T	SEQUENTIAL	NUMBER				
Oyster Creek	Unit 1	0 5 0 0 0 2 h 9	8 19	-	0 2 5	- 0[1	0 2 05	0 4		

DATE OF OCCURRENCE

ant time NAC Form 3884 's/ (17)

This event occurred on December 16, 1989, at 0533 hours. This event was determined to be reportable on March 22, 1990.

IDENTIFICATION OF OCCURRENCE

Two control rods (EIIS Code AA) were selected and moved simultaneously. This occurred while a Control Room Operator was increasing power with control rods. This event is reportable based on 10CFR50.73(a)(2)(ii).

CONDITIONS PRIOR TO OCCURRENCE

The reactor was in the RUN mode with a reactor coolant temperature of 520°F. Generator output was approximately 380 MWe. The initial positions of the two affected control rods were: rod 14-27 at position 48 (fully withdrawn), and rod 18-27 at position 12.

DESCRIPTION OF OCCURRENCE

On December 16, 1989, at 0533 hours, a Control Room Operator (CRO) was increasing power with control rods. The CRO intending to select control rod 18-27 inadvertently selected an adjacent rod 14-27. Realizing the error, the CRO selected the proper control rod at the same time that the rod select push button for the wrong control rod was being released. This resulted in both rods being inadvertently selected at the same time. The CRO did not realize that two control rods were selected and attempted to withdraw rod 18-27 by taking the rod control switch to the "Notch Out" position. The reactor manual control system (EIIS Code JD) withdrawal sequence momentarily inserts the control rod to unlatch the rod so it can be withdrawn. The CRO immediately recognized that both control rods were moving in and quickly took action to stop rod motion by turning off rod select power. This resulted in both rods returning to their original positions. Plant management was immediately notified.

APPARENT CAUSE OF OCCURRENCE

This event was caused by personnel error. The two control rod select switches 14-27 and 18-27 and adjacent to one another. The CRO depressed the rod select push button for control rod 18-27 at the same time that the rod select push button for the wrong control rod 14-27 was being released.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION							U.S NUCLEAR REGULATORY COMMISSION APPROVED ONE NO. 3150-0104 EXPIRES 6/31/85						
FACILITY NAME (1)	DOCKET NUMBER (2)			LER NUMBER (6)					PAGE (3)				
		ļ	YEAR	T	5		MEER	T	NUMBER	T			
2 Oyster Creek, Unit 1	0 15 10 10 10 12 11 1	9	8 9	-	- 0	0 12	15	-	011	0	β	OFO	14
TEXT IN more space & requires, use colditional NRC Form JBA's/ (17)	enter and a strength of the sector of the se							-	*****				

ANALYSIS OF OCCURRENCE AND SAFETY ASSESSMENT

The Reactor Manual Control System (RMCS) (EIIS Code JD) utilizes relay sequencing to control the operation of solenoid operated valves in the Control Rod Drive Hydraulic System. These valves direct high pressure water to the control rod drive mechanism in order to move the control rod. Various switch contacts, including the rod select push button contacts, and an automatic sequencing timer within the system are utilized in the relay control logic.

Circuitry within the reactor manual control system is intended to prevent the selection of more than one control rod at a time. This circuitry can be defeated if contacts within the rod select push button are not properly made or disconnected when a rod select push button is actuated. This can occur when a rod select pushbutton is held mid position and another rod select pushbutton is depressed such as occurred during this event, or, it could occur as a result of a rod select pushbutton malfunction. There is no single component failure that would cause more than two control rods to be withdrawn at the same time. Therefore, this analysis considers only two control rods being withdrawn at one time due to an operator error or single component malfunction.

A Safety Evaluation was performed to determine whether the simultaneous movement of two control rods was outside the design basis for Oyster Creek and, therefore, might constitute an unreviewed safety question. The following were analyzed with respect to the event: Single Failure Criteria, Rod Worth Minimizer (EIIS Code ID) Operation, Uncontrolled Control Rod Withdrawal from a Subcritical or Low Power Startup Condition, Uncontrolled Control Rod Withdrawal at Power, and the Control Rod Drop Accident. The safety functions of the three systems that could be affected by the event were evaluated. Those systems are the Reactor Manual Control System, the Rod Worth Minimizer and the Reactor Protection System. (EIIS Code JC).

The Safety Evaluation concluded that the simultaneous movement of two control rods while the head is on the reactor vessel is within the design basis of the Oyster Creek Plant for the affected transients at power. To address a rod drop accident possibility or a continuous control rod withdrawal from low power, a second CRO (in addition to the RWM) will be used to assure that no single failure will move two rods simultaneously at startup.

The significance of this event was further mitigated by the fact that one of the two control rods was already fully withdrawn to position 48.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED IDMS NO. 3150-0104

FACILITY NAME (1)	DOCKET NUMBER (2)					PAGE (3)			
		YEAR	Γ	SEQUENT	AL	NUMBER			
Oyster Creek, Unit 1	0 15 10 10 10 12 11 1	9 8 19	-	021	5 -	- 011	01	4 05	0 14

CORRECTIVE ACTIONS

Immediate

Reactor manual control system rod control power was secured. This stopped the rod withdrawal sequence and allowed the affected control rods to return to their original positions.

Rod 18-27 was subsequently withdrawn to its programmed position (Notch 14) to provide a symmetrical rod pattern.

An administrative rod block was initiated which prevented any further withdrawal of control rods.

The operability of the rod select/deselect and control rod positioning functions of the Reactor Manual Control System were tested and were found to be satisfactory. A second licensed operator was stationed at the control panel to verify that only one rod was selected during the withdrawal/insertion of control rods.

Long Term

Plant Procedures will be revised to include provisions to minimize the probability of inadvertent simultaneous withdrawal of two control rods where appropriate.

The event will be studied further to include transients with the vessel head removed to determine if any additional testing, maintenance or modifications are warranted. A supplemental LER will be submitted when the ongoing evaluations have been finalized.

SIMILAR OCCURRENCES

None