

The Light Company

Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483

May 15, 1990
ST-HL-AE-3462
File No.: G26
10CFR50.73

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 2
Docket No. STN 50-499
Licensee Event Report 90-005 Regarding a Reactor Trip
Due to Failure of a Main Turbine Electrohydraulic Control Line

Pursuant to 10CFR50.73, Houston Lighting & Power Company (HL&P) submits the attached Licensee Event Report (LER 90-005) regarding a reactor trip due to failure of a main turbine electrohydraulic control line. This event did not have any adverse impact on the health and safety of the public.

If you should have any questions on this matter, please contact Mr. C. A. Ayala at (512) 972-8628 or myself at (512) 972-7921.

G. E. Vaughn
G. E. Vaughn *by [Signature]*
Vice President
Nuclear Generation

BEM/nl

Attachment: LER 90-005 (South Texas, Unit 2)

9005230116 900515
PDR ADQCK 05000499
S PDC

A1/LER005U2.L01

A Subsidiary of Houston Industries Incorporated

TE22
11

Houston Lighting & Power Company
South Texas Project Electric Generating Station

ST-HL-AE-3462
File No.: G26
Page 2

cc:

Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

George Dick, Project Manager
U.S. Nuclear Regulatory Commission
Washington, DC 20555

J. I. Tapia
Senior Resident Inspector
c/o U. S. Nuclear Regulatory
Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire
Newman & Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

D. E. Ward/R. P. Verret
Central Power & Light Company
P. O. Box 2121
Corpus Christi, TX 78403

J. C. Lanier
Director of Generation
City of Austin Electric Utility
721 Barton Springs Road
Austin, TX 78704

R. J. Costello/M. T. Hardt
City Public Service Board
P. O. Box 1771
San Antonio, TX 78296

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 61867
Houston, TX 77208

INPO
Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

Dr. Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

D. K. Lacker
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78704

Revised 12/15/89

L4/NRC/

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) South Texas, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 4 9 9	PAGE (3) 1 OF 0 3
--	--------------------------------------	----------------------

TITLE (4)
Reactor Trip Due to Failure of a Main Turbin Electrohydraulic Control Line

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 4	1 4	9 0	9 0	0 0 5	0 0	0 5	1 5	9 0			0 5 0 0 0
0 5 0 0 0											

OPERATING MODE (8) 1

POWER LEVEL (10) 1 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input checked="" type="checkbox"/> 50.73(e)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.406(e)(1)(i)	<input type="checkbox"/> 50.36(e)(1)	<input type="checkbox"/> 50.73(e)(2)(v)	<input type="checkbox"/> 73.71(e)
<input type="checkbox"/> 20.406(e)(1)(ii)	<input type="checkbox"/> 50.36(e)(2)	<input type="checkbox"/> 50.73(e)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 20.406(e)(1)(iii)	<input type="checkbox"/> 50.73(e)(2)(i)	<input type="checkbox"/> 50.73(e)(2)(vii)	
<input type="checkbox"/> 20.406(e)(1)(iv)	<input type="checkbox"/> 50.73(e)(2)(ii)	<input type="checkbox"/> 50.73(e)(2)(viii)(A)	
<input type="checkbox"/> 20.406(e)(1)(v)	<input type="checkbox"/> 50.73(e)(2)(iii)	<input type="checkbox"/> 50.73(e)(2)(viii)(B)	
<input type="checkbox"/> 20.406(e)(1)(vi)	<input type="checkbox"/> 50.73(e)(2)(iv)	<input type="checkbox"/> 50.73(e)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME Charles Ayala - Supervising Licensing Engineer	TELEPHONE NUMBER 5 1 2 9 7 2 - 8 6 2 8
--	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On April 14, 1990, Unit 2 was in Mode 1 at 100 percent power. At 1704 hours, a simultaneous reactor and turbine trip occurred on low turbine electrohydraulic control (EHC) fluid pressure. The plant was brought to a stable shutdown in Mode 3 with no unexpected post-trip transients. The cause of this event was failure of the EHC supply line to a main turbine governor valve. The line failed due to fatigue stress of a weld caused by governor valve-induced vibration. The valve vibration was caused by valve plug rotation. Interim corrective action has been taken to repair the EHC supply piping and add additional supports. The valve used to throttle flow during full power operation will be modified to add anti swirl baffles and anti rotation pins on the plug to stem connection during the first refueling outage.

A1/LER005U2.L01

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) South Texas, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 4 9 9 9 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 0	0 0 5	0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT:

On April 14, 1990, Unit 2 was in Mode 1 at 100 percent power. At 1704 hours, a simultaneous reactor and turbine trip occurred on low turbine electrohydraulic control (EHC) fluid pressure. Workers in the area of the main turbine governor valves reported the rupture of an EHC line to one of the governor valves. A feedwater isolation occurred on low Reactor Coolant System average temperature and an Auxiliary Feedwater System actuation occurred on low steam generator level as expected. The main steam isolation valves were closed to limit the cooldown and the steam generator power operated relief valves (PORV) were used to control temperature. The plant was stabilized in Mode 3.

Investigation of this event revealed that the weld on the EHC supply line to the governor valve had failed at the tube side toe of the weld where it connected to a tee in the supply header. The weld was cut out, rewelded and dye penetrant examined for integrity. At the time, it was believed that the failure had resulted from recent maintenance activities on the governor valve.

On April 25, 1990, following restart of the unit, dye penetrant inspection of the new weld showed a new linear indication. Dye penetrant inspections of other welds of EHC piping on Unit 2 were then performed and additional linear indications were found. Metallurgical examination of the original failure site indicated fatigue failure with origins at multiple locations around the circumference of the pipe. Observation of the Unit 2 EHC piping during plant operation indicated that significant vibration occurred concurrent with vibration of the governor valve. The cyclic stress from the governor valve-induced vibration could have resulted in the earlier fatigue failure. Temporary supports were added which greatly reduced the vibration amplitude. Inspections of Unit 1 EHC piping did not reveal any cracks.

CAUSE OF EVENT:

The cause of the reactor trip was a loss of EHC pressure due to a supply line failure. The line failed due to fatigue stress of a weld caused by governor valve induced vibration.

The cause of the governor valve vibration has been determined to be valve plug rotation.

A1/LER005U2.L01

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) South Texas, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 4 9 9	LER NUMBER (6)			PAGE (3)		
		YEAR 9 0	SEQUENTIAL NUMBER 0 0 5	REVISION NUMBER 0 0			
					0 3	OF	0 3

TEXT (if more space is required, use additional NRC Form 306A's) (17)

ANALYSIS OF EVENT:

Unplanned Reactor Trip System actuation is reportable pursuant to 10CFR50.73(a)(2)(iv). The plant was brought to a stable shutdown in Mode 3. There were no unexpected post trip transients.

CORRECTIVE ACTION:

The new linear indications found on the EHC supply piping have been evaluated and repaired as required.

In the interim, to compensate for the cause of the vibration and limit its effects the following actions are being taken:

1. As a conservative measure, additional supports have been added to the EHC lines on Unit 2 to dampen any unusual vibration.
2. The governor valve control logic has been changed such that the valve which vibrated during operation is now maintained fully open at full load and another valve is modulated to vary turbine load.

The valve used to throttle flow during full power operation will be modified to add anti swirl baffles and anti rotation pins on the plug to stem connection during the first refueling outage. The remaining valves will be modified as schedule permits.

ADDITIONAL INFORMATION:

There have been no previous events reported regarding reactor trips due to failed EHC piping.

A1/LER005U2.L01