RC FORM 366 U. S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT CONTROL BLOCK IPLEASE PRINT OR TYPE ALL REQUIRED INFORMATION A S P S 1 0 0 - 0 0 0 0 - 0 0 0 4 1 1 1 1 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TY 011 CONT REPORT 0 1 SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) With unit no. 1 at 100% power, PT-27 revealed that amp readings for heat tracing 0 21 panels 8 & 9, circuits 24A & C, were below the acceptance criteria stipulated. 0 3 This event is contrary to T.S.3.2.B.5 and is reportable per T.S.6.6.2.b.(2) 0 4 Flow was verified by PT-18.4 and adjacent circuits were operable. Therefore, the 0 5 0 16 health and safcty of the public were not affected 0 7 SIC SYSTEM CAUSE CAUSE COMP SUBCODE CODE COMPONENT CODE SUBCODE E 12 A 13 H (16) 0 9 R (14 (15) Z 18 REVISION SEQUENTIAL REPORT NO. OCCURRENCE CODE EVENT YEAR LER/RO NO. REPORT 0 1 7 013 0 -COMPONENT NPRD-4 SUBMITTED PRIME COMP TAKEN ACTION METHOD HOURS 22 ONFLANT FORM SUB SUPPLIER MANUFACTURER N 24 18 Y 23 A 25 Z 20 0 0 0 0 0 T | 1 | 8 | 5 F (19) Z (21) 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27 The loss of heat tracing was due to excessive heat. The defective heat tracing was 1 0 replaced and tested. A design change has been initiated to change the manner by 1 1 which these borated lines are heat traced. 1 3 1 4 80 METHOD OF FACILITY OTHER STATUS 30 DISCOVERY DESCRIPTION (32) % POWER E 28 1 01 0 29 B (31) 1 5 Routine ACTIVITY CONTENT 80 AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) RELEASED_OF RELEASE Z 33 LZ 34 1 6 10 80 PERSONNEL EXPOSURES DESCRIPTION (39 NUMBER TYPE (38) 0 N/A 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER (40) 18 0 0 N/A 80 OSS OF OR DAMAGE TO FACILITY (43) 1 9 N/A 80 PUBLICITY B203180318 B20301 PDR ADDCK 05000280 NRC USE ONLY N 44 DESI N/A 1111111111 68 6.0 80 PDR (804) 357-3184 NAME OF PREPARES _ J. DUTNE

ATTACHMENT 1 SURRY POWER STATION, UNIT NO. 1 DOCKET NO: 50-280 REPORT NO: 82-017/03L-0 EVENT DATE: 01-31-82

TITLE OF THE EVENT: HEAT TRACING FAILURE

1. DESCRIPTION OF EVENT:

With unit no. 1 at 100% power, performance of PT-27 revealed that the amp readings for heat tracing panels 8 and 9, circuit 24A (Unit #1 Filter 1-CH-FL-1) and Panel 9, circuit 24C (Flow Transmitter FT-1110) were below the acceptance criteria stipulated in the PT. This event is contrary to Technical Specification 3.2.B.5 and is reportable per Technical Specification 6.6.2.b(2).

2. PROBABLE CONSEQUENCES AND STATUS OF REDUNLANT EQUIPMENT:

The heat tracing circuits are intended to maintain a fluid temperature above that needed for flow. Performance of PT 18.4 verified flow through the unit 1 filter. The redundant heat tracing circuits on the pipes adjacent to the flow transmitter vere operable. Therefore, the health and safety of the public were not affected.

3. CAUSE:

4.

The loss of heat tracing was due to excessive heat.

4. IMMEDIATE CORRECTIVE ACTION:

The immediate corrective action was to verify flow by performance of PT-18.4 and to verify that adjacent circuits were operable.

5. SUBSEQUENT CORRECTIVE ACTION:

The defective heat tracing tape was replaced and tested within the time span specified by Technical Specifications.

6. ACTION TAKEN TO PREVENT RECURRENCE:

No additional actions were deemed necessary.

7. GENERIC IMPLICATIONS:

A task force has reviewed the total spectrum of the Heat Tracing System and a Design Change has been prepared as a result of the Task Force Study. Installation of this design change has commenced.