LICENSEE EVENT REPORT

	CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 ;	N C B E P 1 3 0 0 - 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T	SOURCE L 6 0 5 0 - 0 3 2 5 0 0 12 1 0 8 2 8 0 3 1 1 8 2 9
0 2	While shutdown, performance of the Main Turbine Control Valve Fast Closure-Response
0 3	Time Test, PT 45.1.7, revealed that main turbine control valve hydraulic control oil
0 4	pressure switch, 1-EHC-PSL-1758, would not actuate. This switch provides an "A"
0 5	channel scram logic input when EHC oil pressure decreases to ≤ 500 psig. The other
0 [6]	3 redundant pressure switches were tested and found operable and would have initiated
0 7	a scram signal on receipt of an actual low hydraulic oil pressure. This event did not
0 8	affect the health and safety of the public. T.S. 1.1, 6.9.1.9a
7 8	SYSTEM CODE CODE SUBCODE SUBCO
	TO REPORT NUMBER 21 23 25 25 26 27 27 27 28 28 29 29 29 29 29 29 29 29 29 29 29 29 29
	ACTION FUTURE EFFECT SHUTDOWN METHOD 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	The cause of this event could not be determined. The switch was removed and bench-
111	tested and found to operate within specified tolerances. In order to prevent future
[1]	similar events with this switch, it was replaced with an identical switch, Model No.
	TC-9622-3, and returned to service. As plant documentation shows, this event is
7 8	isolated, no further corrective actions are planned.
1 5 EA	G 28 0 0 0 0 2 NA METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
	LEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) NA LOCATION OF RELEASE (36)
1771	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA NA
7 8 9	PERSONNEL INJURIES NUMBER DESCRIPTION (41)
7 8 9	0 0 0 40 NA
191	OSS OF OR DAMAGE TO FACILITY (43) Z (42) NA
7 8 9	PUBLICITY 80
PDR ADI	0206 820311 DCK 05000325
S	PDR 80 50 5