

LICENSEE EVENT REPORT

Update Report
Previous Report Date 3-4-82

CONTROL BLOCK: _____ (1)
(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | C | B | E | P | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | _____ | _____ | 4 | _____ | _____ | 5
7 8 9 | 14 | 15 | 25 | 26 | 30 | 57 | CAT 58

CON'T
0 1 | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 2 | 4 | 7 | 0 | 2 | 0 | 9 | 8 | 2 | 8 | 0 | 3 | 1 | 2 | 8 | 2 | 9
7 8 | 60 | 61 | DOCKET NUMBER | 68 | 69 | EVENT DATE | 74 | 75 | REPORT DATE | 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | _____
0 3 | _____
0 4 | _____
0 5 | _____
0 6 | _____
0 7 | _____
0 8 | _____
0 9 | _____

_____ Technical Specifications 3.3.5.3, 3.6.6.4, 6.9.1.9b _____
7 8 9

0 9 | S | E | 11 | E | 12 | A | 13 | I | N | S | T | R | U | 14 | Y | 15 | Z | 16
7 8 | 9 | 10 | 11 | 12 | 13 | 18 | 19 | 20

17 LER RO REPORT NUMBER | 8 | 2 | 21 | 22 | _____ | 23 | 0 | 3 | 1 | 24 | 26 | _____ | 27 | 0 | 3 | 28 | 29 | L | 30 | _____ | 31 | 1 | 32

ACTION TAKEN | C | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | Y | 23 | Y | 24 | A | 25 | N | 3 | 0 | 5 | 26
31 | 34 | 35 | 36 | 37 | 40 | 41 | 42 | 43 | 44 | 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | _____
1 1 | _____
1 2 | _____
1 3 | _____
1 4 | _____
7 8 9 Is required. _____

FACILITY STATUS | E | 28 | 0 | 7 | 8 | 29 | NA | 30 | A | 31 | Plant Technician Surveillance | 32
7 8 9 | 10 | 12 | 13 | 44 | 45 | 46

ACTIVITY CONTENT RELEASED | Z | 33 | Z | 34 | NA | 35 | NA | 36 | LOCATION OF RELEASE | 36
7 8 9 | 10 | 11 | 44 | 45

PERSONNEL EXPOSURES | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 | 10 | 11 | 12 | 13

PERSONNEL INJURIES | 0 | 0 | 0 | 40 | _____ | 41
7 8 9 | 10 | 11 | 12

LOSS OF OR DAMAGE TO FACILITY | Z | 42 | NA | 43
7 8 9 | 10

PUBLICITY | _____ | 45 | _____ | 46
7 8 9 | 10 | 11 | 12

8204020223 820312
PDR ADDOCK 05000324
S PDR

LER ATTACHMENT - RO #2-82-31

Facility: BSEP Unit No. 2

Event Date: 2-9-82

During plant operation, while performing their routine duties, two plant technicians in the vicinity of primary containment atmospheric monitor, 2-CAC-ATH-1259, detected an unusual odor emanating from the monitor cabinet. This monitor is located on the 20-foot elevation of the Reactor Building. Further investigation revealed water was dripping down on the top of the cabinet from the 50-foot elevation. This water had entered the cabinet and made contact with the monitor main power transformer causing it to electrically short, which resulted in the detected odor.

Immediate notification of the 1259 monitor problem was then made to the Control Room. Power supplying the affected monitor transformer was secured. In addition, a temporary water deflector was installed above the monitor cabinet to prevent further intrusion of water into the monitor components.

A search for the source of the leak revealed the dripping water had originated from a small valve body flange gasket leak on the RHR service water header flushing valve 2-SW-V140 located on the 50-foot elevation of the Reactor Building. This valve serves to isolate well water used to flush either RHR service water subsystem. As the leak occurred on the upstream side of the valve body, the water involved was well water.

Following isolation of the leak, the affected 1259 monitor transformer was replaced and the monitor was returned to normal service. The defective valve flange gasket was then replaced with one of greater strength and durability than the original and the valve was returned to normal service. It is felt that the performed corrective actions in response to this event are appropriate and need no further follow-up.