LICENSEE EVENT REPORT
CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 57 CAT 58 5
REPORT SOURCE L 6 0 5 0 - 0 3 2 5 7 0 2 1 6 8 2 8 0 3 1 7 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During plant operation, the RCIC Turbine Tripped annunciation was received and an
0 3 immediate check of the RTGS indication for the RCIC turbine trip/throttle valve,
0 4 1-E51-V8, showed it had tripped, making the RCIC System inoperable. At the time of
this event, the HPCI System was operable. This event did not affect the health and
0 6 safety of the public.
Technical Specification 6.9.1.9b
0 8 6
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUB
The RCIC turbine local mechanical trip device was found tripped. The device was
[1] reset and the RCIC System was returned to service. An investigation will be
[1 2] [conducted to determine the cause of the trip. A supplement to this report will
13 follow.
1 4 L 7 8 9
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 9 1 29 NA A 31 Operational Event 7 8 9 10 12 13 44 45 46 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (3E) NA LOCATION OF RELEASE (36)
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 8 9 11 12 13 PERSONNEL INJURIES 80
1 B 0 0 0 (40) NA
Type Description NA 80
PI 8204020348 820317 SSUET PDR ADOCK 05000325 PDR NA
M. J. Pastva, Jr. (919) 457-9521