



LER SUPPLEMENTAL INFORMATION

BFRO-50- 260/ 8211 Technical Specification Involved Table 3.2.F

Reported Under Technical Specification 6.7.2.a \* Date Due NRC 3/16/82

Event Narrative:

Units 1 & 2 normal operation, unit 3 in refueling outage. Unit 2 was affected by this event. During performance of SI 4.7.A.1.a (Suppression Chamber Water Check), Level Indicator 2-LI-64-66 was observed to indicate improper torus level and declared inoperable, Technical Specification (TS) Table 3.2.F.

Calibration was performed on 2-LT-64-66, Level Transmitter, per SI 4.2.F-7 and found out of calibration (6.4%) or 3.2". The level transmitter was calibrated and returned to service. There was no danger to the health or safety of the public because a redundant indicator was available and operable. The observed improper level was due to instrument drift or possibly air in the reference leg of the transmitter.

\* Previous Similar Events:

BFRO-50-260/81051; 296/81053

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: JRR