Detroit Edison Donald A. Wells

Manager Quality Assurance (213) 237-9657

2000 Second Avenue Detroit, Michigan 48226 (313) 237 8000



March 23, 1982 EF2-57460

Mr. James G. Keppler, Director Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Interim Report of 10CFR50.55(e) Item on Emergency Diesel Generator Relay Failures (#59)

Dear Mr. Keppler:

On February 22, 1982, Detroit Edison's Mr. H.A. Walker, Supervisor-Construction Quality Assurance, telephoned Mr. P. Pelke of NRC-Region III, to report on a problem with Emergency Diesel Generator Relay Failures at the Fermi 2 site.

Detroit Edison has had a number of relay failures in the control circuitry of the emergency diesel generator for Division I. On diesel generator number twelve, six of eleven relays tested did not operate properly. The failure of these relays would prevent the diesel generator from starting. These relays were manufactured by ITE, and were supplied to Fermi 2 by Colt with the diesel generator. These relays were previously located on panels attached to the diesel generator, but were relocated to a separate panel to eliminate vibration. It is not known at this time, if the failure is due to a manufacturing problem with the relays or possible damage sustained during the relocation. Detroit Edison is investigating this problem.

Another report or this item, either interim or final, is scheduled to be sent to you on or before July 22, 1982. If you have questions concerning this matter, please contact Mr. H.A. Walker, Supervisor-Construction Quality Assurance.

Very truly yours,

DAW/HAW/cp

MAR 2 6 1982

Milleds

5/1/0 IE 27 cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
U.S. Nuclear Regulatory Commission
6450 North Dixie Highway
Newport, Michigan 48166

Mr. Bruce Little, Resident Inspector U.S. Nuclear Regulatory Commission 6450 North Dixie Highway Newport, Michigan 48166