

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1														
7	8														

REPORT SOURCE

L	(6)	0	5	0	-	0	3	2	5	(7)	0	2	2	2	8	2	(8)	0	3	2	3	8	2	(9)		
60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 8 Technical Specifications 3.41.1., 6.9.1.9b 8

09		SYSTEM CODE I B 11		CAUSE CODE A 12		CAUSE SUBCODE C 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE T 15		VALVE SUBCODE Z 16	
7 8		9 10		11		12		13 14 15 16 17 18				19 20		21 22	
17		EVENT YEAR 8 2		—		SEQUENTIAL REPORT NO. 0 3 3		OCCURRENCE CODE /		REPORT TYPE L		—		REVISION NO. C	
21 22		23 24		25 26		27 28		29 30		31 32		33 34		35 36	
ACTION TAKEN X 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER A 25	
33 34		35 36		37 38		39 40		41 42		43 44		45 46		47 48	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)															

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Plant technicians misinterpreted the PT procedure and unknowingly bypassed redundant
1 1 instrument NO24B-2 rather than NO25B-2, which was under test, resulting in actuation
1 2 of NO25B-2 when a test signal was applied. Involved personnel were counseled on the
1 3 importance of proper interpretation of test procedures. A review of maintenance
1 4 procedures is in progress to identify and correct misleading instructions.

FACILITY STATUS (1) 5 (E) (28) % POWER (0) 8 (3) (29) OTHER STATUS (30) NA
 ACTIVITY CONTENT RELEASED OF RELEASE (1) 6 (Z) (33) (Z) (34) NA AMOUNT OF ACTIVITY (35)
 METHOD OF DISCOVERY (B) (31) Periodic Test DISCOVERY DESCRIPTION (32)
 LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	40	NA

8		9		10		11		12		
LOSS OF OR DAMAGE TO FACILITY						(43)				
TYPE		DESCRIPTION								
1	9	Z	(42)	NA						

ISSUED (2) (0) (N) PUBLICITY DESCRIPTION (45) 8204080070 820323 PDR AD0CK 05000325 S PDR NA 68 69 90 NRC USE ONLY

Facility: BSEP Unit No. 1

Event Date: February 22, 1982

During plant operation, while performing RPT System reactor low water level number 2 channel calibration and functional test, PT-A5, plant technicians inadvertently actuated ATWS-RPT instrument, 1-B21-LTM-N025B-2, Rosemount Model No. 510DU, resulting in a trip of 1B reactor recirculation pump.

This event occurred due to misinterpretation of a section of the PT procedure which requires bypassing the low level/high pressure signal input to the N025B-2. Plant technicians mistakenly associated bypass switch position B, for redundant instrument N024B-2, as the required bypass switch position for N025B-2. The bypass switch position for N025B-2 is identified in the PT procedure as switch position D. As a result, actuation of N025B-2 occurred when a test signal was applied to it with the N024B-2 instrument bypassed.

After the cause of this event was determined, the incurred trip signal was reset and the pump was restarted. The PT was then satisfactorily completed. The involved plant technicians have been counseled on the importance of proper procedure interpretation. In addition, a review of maintenance procedures is in progress to identify and correct misleading test instructions.