

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | C | M | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 14 15 25 26 30 37 58

CON'T

01 | R | E | P | O | R | T | S | O | U | R | C | E | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 9 | 7 | 0 | 2 | 1 | 2 | 8 | 2 | 8 | 0 | 3 | 2 | 4 | 8 | 2 | 9

7 8 60 61 66 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | While in mode 1, during an attempt to fill and vent the reciprocating charging

03 | pump (PD) suction piping in preparation for returning the pump to service, both

04 | centrifugal charging pumps (CCP) were declared inoperable when hydrogen from the

05 | PD pump suction dampeners entered the suction of the CCP's causing cavitation.

06 | This violates T.S.3.1.2.4, 3.1.2.2, and 3.5.2 which is reportable per T.S.6.9.1.

07 | 12(e). Since the unit remained in a steady state condition until charging and

08 | letdown were restored, the health and safety of the public were unaffected.

7 8 9

09 | SYSTEM CAUSE CAUSE COMPONENT COMP. VALVE

7 8 9 10 11 12 13 14 15 16 17 18 19 20

09 | P | C | 11 | E | 12 | X | 13 | X | X | X | X | X | 14 | Z | 15 | Z | 16

17 | LER/NO REPORT NUMBER | 8 | 2 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 1 | 5 | 24 | 25 | OCCURRENCE CODE | 0 | 1 | 26 | 27 | REPORT TYPE | T | 28 | 29 | REVISION NO. | 0 | 30 | 31 |

ACTION TAKEN | X | 18 | X | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NRC-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | Z | 25 | COMPONENT MANUFACTURER | Z | 9 | 9 | 9 | 26

33 34 35 36 37 38 39 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | This incident resulted from the failure of the Hydrogen Control System on the PD

11 | pump suction dampener (the reference pot and leg were found empty, cause unknown).

12 | Immediate corrective action was to secure the CCP's, isolate the PD pump suction,

13 | vent the CCP's and suction piping, and return the CCP's to service. Use of the

14 | PD system will be discontinued until corrective action to prevent recurrence can

7 8 9 be determined and taken.

15 | FACILITY STATUS | B | 28 | % POWER | 0 | 5 | 0 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Personnel Observation | 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 | ACTIVITY CONTENT | Z | 33 | Z | 34 | N/A | 35 | AMOUNT OF ACTIVITY | LOCATION OF RELEASE | N/A | 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | N/A | 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | N/A | 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NRC USE ONLY

55 56 57 58 59 60

B204080077 B20324
PDR ADOCK 05000369
PDR
S

ip B. Nardori

PHONE: (704) 373-7432