



# SUPPLEMENTARY INFORMATION

Report No.: 50-302/82-011/03L-0

Facility: Crystal River Unit 3

Report Date: March 17, 1982

Occurrence Date: February 24, 1982

## Identification of Occurrence:

Failure of Channel "A", RC flow, to calibrate during Surveillance Procedure SP-112 performance. This created an event not attributed to a specific shutdown activity as required by Regulatory Guide 1.16, and, therefore, contrary to Technical Specification 3.3.1.1.

## Conditions Prior to Occurrence:

Mode 5 cold shutdown (0%).

## Description of Occurrence:

At 1800, during performance of Surveillance Procedure SP-112, RC flow, Channel "A" was found out of calibration. Maintenance was initiated and operability was restored on February 25, 1982.

## Designation of Apparent Cause:

The cause of this event is attributed to the linear voltage differential transformer shorting out.

## Analysis of Occurrence:

There was no effect upon the health or safety of the general public.

## Corrective Action:

The linear voltage differential transfmformer was replaced and the instrument was calibrated per Surveillance Procedure SP-112. No further corrective action is deemed necessary.

## Failure Data:

This is the second occurrence for RC flow, Channel "A", and the eleventh report under this Specification.

/rc