

## LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ]

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | S | L | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5  
L 4 S 3 LICENSE CODE 14 5 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38 5

REPORT SOURCE L 5 0 5 0 0 0 3 3 5 7 0 2 1 8 8 2 3 0 3 2 4 8 2 9

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0 2 | While at 98% power, the Shield Bldg. Ventilation System heater 6B2 was  
0 3 | found to be inoperable. The 1.5 KW 6B2 heater provides humidity control  
0 4 | in the "A" SBVS while the "B" SBVS is operating. The 30 Kw 6A1 heater  
0 5 | was available for humidity control with "A" train running. All other  
0 6 | aspects of both SBVS train have been operable since the last TS 4,6,6,1a  
0 7 | surveillance. The health and safety of the public was not affected.

This is second event of type. See LER 80-014.

A defective thermocouple amplifier (Fenwal model No. 543) in the 6B2 heater control circuitry caused the heater to remain deenergized. The amplifier was repaired and the heater was retested.

1 4

FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY (32) DISCOVERY DESCRIPTION (32)  
E | 0 | 9 | 8 | 29 | NA | B | 31 | Routine Surveillance

7 8 9 10 11 12 13 14 15 16 17  
ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  
1 6 Z (33) Z (34) NA  
LOCATION OF RELEASE (26)

7 3 3 10 11  
PERSONNEL EXPOSURES  
NUMBER TYPE DESCRIPTION (39)  

01	010	1212	NA
----	-----	------	----

7 8 9 10 11 12 13 30  
PERSONNEL INJURIES  
NUMBER DESCRIPTION (41)

1 3 0 0 0 0 40 NA 30  
7 8 9 10 11 12 LOSS OF OR DAMAGE TO FACILITY 41

NA

ISSUED **N** DESCRIPTION **NA** MAIL USE ONLY

NAME OF PREPARER P. L. Pace PHONE (305) 552-3654  
8204880125 6200251

8204080195 820324  
PDR ADDOCK 05000335  
S PDR