
HISTORY OF VERMONT YANKEE
FEEDWATER SPARGER
MODIFICATIONS AND FUTURE
PLANS

- LIQUID PENETRANT INSPECTION OF NOZZLES REVEALED CLAD CRACKS

  AT BLEND RADIUS PRIMARILY AT THE 1800 (BOTTOM) LOCATION AFTER

  FOUR (4) YEARS OPERATION
- NO BORE CRACKS
- MAXIMUM DEPTH AT ANY GRINDOUT = .3125" TOTAL DEPTH AT 1750 LOCATION
- SHALLOWEST DEPTH OF ANY BWR WHICH EMPLOYED A LOOSE FIT SPARGER
- CRACKS GROUND OUT
- NEW INTERFERENCE FIT FEEDWATER SPARGERS INSTALLED ALONG WITH JUNCTION BOX TEE
- INTERFERENCE FIT THERMAL SLEEVE SEATING SURFACE IS INCONEL WITH A .010" .013" INTERFERENCE
- STAINLESS STEEL CLADDING WAS NOT REMOVED
- STARTUP OPERATING PROCEDURES MODIFIED TO REDUCE FEEDWATER
  FLOW CYCLING AND MINIMIZE OPERATING TIME AT LOW FEEDWATER
  TEMPERATURES

## VERMONT YANKEE FEEDWATER SPARGER THERMAL SLEEVE



- IN VESSEL LIQUID PENETRANT EXAMINATION PERFORMED ON INNER
  BLEND RADIUS OF EACH NOZZLE WITH SPARGERS IN PLACE
- EXAM EXTENDS ABOUT 5" INTO BORE AT 00 AND 1800 SECTORS
- NO INDICATIONS FOUND

- SECOND IN-VESSEL LIQUID PENETRANT EXAM PERFORMED SINCE
  INSTALLATION OF INTERFERENCE FIT SPARGERS
- NO INDICATIONS FOUND

- NUREG-0619 ISSUED FOR COMMENT
- VERMONT YANKEE STATES DISAGREEMENT WITH NUREG CONCLUSION
  THAT INTERFERENCE FIT SPARGER THERMAL SLEEVE IS NOT A LONG
  TERM SOLUTION TO NOZZLE CRACKING PROBLEM

- JANUARY, 1981 NUREG-0619 ISSUED
- INTERFERENCE FIT FEEDWATER SPARGERS ARE NOT CONSIDERED
  A LONG TERM FIX AND SHOULD BE REPLACED BY 7/83
- IN INTERIM, CONTINUE BIENNIAL OR 30 STARTUP SHUTDOWN IN-VESSEL LIQUID PENETRANT EXAMS

### APRIL 1981

DATA SUPPORTING OUR POSITION THAT THE INTERFERENCE FIT

SPARGER WAS PERFORMING VERY WELL AND DID NOT REQUIRE

REPLACEMENT

### BASIS FOR JUSTIFICATION

- OR NO BYPASS LEAKAGE WHICH IS NEEDED TO INITIATE CRACKING
- LOWER RADIATION EXPOSURE BY INSPECTING THAN REPLACING SPARGERS
- OPERATING PROCEDURES WHICH MINIMIZE FEEDWATER FLOW CYCLING
  AND TRANSIENTS
- MUCH REDUCED NUMBER OF CRACK PROPAGATING STARTUP SHUTDOWN
  CYCLES SINCE PLANT "MATURED"
- NO RELEVANT CLAD CRACKING HAS OCCURRED IN BWRS WITH ORIGINAL INTERFERENCE FITS
- INSTALLATION OF BYPASS LEAK DETECTION SYSTEM TO MONITOR
  DELETERIOUS LEAKAGE
- IN GENERAL, THE INTERFERENCE FIT DESIGN HAS SOLVED THE

  NOZZLE CRACKING PROBLEM AT VERMONT YANKEE AND INSUFFICIENT

  JUSTIFICATION EXISTS TO REPLACE SPARGERS AND EXPOSE

  PERSONNEL TO SIGNIFICANT RADIATION

# FEEDWATER TEMPERATURE COMPARISON BETWEEN GENERAL ELECTRIC GENERIC AND VERMONT YANKEE

### HRS/YR

T <sub>FW</sub> (°F)	GENERAL ELECTRIC	VERMONT YANKEE (MATURE OPERATION)
350 - 380	0	7073
300 - 350	5545	312
200 - 300	2354	14
100 - 200	116	53
100	28	16*

<sup>\* 1/6</sup> RATED FLOW

### TEMPERATURE DIFFERENCE MAP

### T<sub>REACTOR</sub> - T<sub>FEEDWATER</sub> HRS/YR

ΔL	YERMONT YANKEE	GENERAL ELECTRIC
450		28
400	16	98
350	21	19
300	36	2354
250	14	5545
200	561	8
175	5824	

### NOVEMBER 1981

- THIRD IN-VESSEL PT EXAMINATION PERFORMED WITH IDENTICAL
  RESULTS
  NO INDICATIONS
- NUTECH BYPASS LEAK DETECTION SYSTEM INSTALLED


### JANUARY 1982

- LETTER SENT TO NRC STAFF PROVIDING INSPECTION RESULTS AND
INITIAL LEAK DETECTION SYSTEM READINGS

### FUTURE PLAN

- CONTINUE TO MONITOR LEAKAGE WEEKLY ON LEAKAGE MONITORING SYSTEM
- PERFORM IN-VESSEL PT EXAMS AT THE CYCLIC INTERVAL (30 STARTUP SHUTDOWNS) SPECIFIED IN NUREG-0619
- CONTINUE TO OBSERVE STARTUP PROCEDURES WHICH REDUCE CYCLING
  OF FEEDWATER FLOW AND TEMPERATURE
- CONTINUE TO OPERATE WITH INTERFERENCE FIT SPARGERS AND CLAD IN PLACE

FEEDWATER NOZZLE TEMPERATURES



NORMLZD. TIC READINGS