

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T
 REPORT SOURCE L 6 0 5 0 0 0 2 4 9 7 0 3 1 7 8 2 1 8 0 3 3 0 8 2 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 During refueling, dripping water within the drywell was traced to a .25 inch through-wall
0 3 crack in the .50 inch head seal leak detection piping located approximately 3 feet from
0 4 vessel flange. This event was of minimal safety significance because all leakage was
0 5 contained in the drywell floor drain system and potential leakage is within the capabil-
0 6 ity of the emergency core cooling systems. First occurrence of this type on the seal
0 7 leak detection system at Dresden.

0 8 9

SYSTEM CODE C I 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE P I P E X X 14 COMP SUBCODE A 15 VALVE SUBCODE Z 16
 LER/RO REPORT NUMBER 8 2 EVENT YEAR 0 1 4 SEQUENTIAL REPORT NO. 0 3 OCCURRENCE CODE L 31 REVISION NO. 0 32
 ACTION TAKEN X 18 FUTURE ACTION B 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPD-4 FORM SUB N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER C 0 9 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The cause of the pipe crack is undetermined. Leakage (approximately 1 drop per minute)
1 1 is located in a section of pipe which can not be isolated. Repair and analysis will be
1 2 accomplished following cavity drain down and reactor vessel head installation. A
1 3 supplementary report will be issued after the completion of repair and analysis.

1 4 9

FACILITY STATUS H 28 % POWER 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32
 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY ISSUED N 44 DESCRIPTION 8204120240 820330 PDR ADOCK 05000249 PDR 45

NAME OF PREPARER G. W. Bergan PHONE 815-942-2920, X-529

ATTACHMENT TO LICENSEE EVENT REPORT 82-014/03L-0
COMMONWEALTH EDISON COMPANY (CWE)
DRESDEN UNIT 3 (ILDRS-3)
DOCKET # 050-249

During the current refueling outage, workers discovered water dripping from the reactor vessel head seal leak detection piping upstream of Valve 3-220-52 approximately three feet from the vessel flange. All leakage was contained inside the drywell and directed to the Drywell Floor Drain System.

Upon further investigation, the leakage was determined to be coming from a .25 inch long through-wall crack in the .5 inch section of piping. The crack was approximately 45° from pipe axis. Calculations show that a complete severance of a .5 inch line such as this would be well within the capabilities of ECCS.

The exact cause of the pipe crack is undetermined at this time. Because the leakage (approximately 1 drop/minute) is not isolatable, repair and analysis will be accomplished following cavity drain down and reactor vessel head installation. An updated report will be issued after completion of repair and analysis.



Commonwealth Edison

DEVIATION REPORT

DVR NO. 12 3 82 20
STA UNIT YEAR NO.PART 1 TITLE OF DEVIATION Discovery of Crack in Unit 3
Head Seal Leakoff Line OCCURRED 3-17-82 1700
DATE TIMESYSTEM AFFECTED 220 PLANT STATUS AT TIME OF EVENT
Head Leak Detection MODE S/D PWR(MWT) 0 LOAD(MWE) 0 TESTING
YES NODESCRIPTION OF EVENT Visual inspection following discovery of dripping water in the drywell
disclosed a small crack (.25 in.) in the head seal leak detection line on the Rx side of
the 3-220-52 valve. The crack is in the .5 in. line.10 CFR50.72 NRC RED PHONE
NOTIFICATION MADE YES NO

EQUIPMENT FAILURE 19350

YES NO WORK REQUEST NO. RESPONSIBLE SUPERVISOR Michael Wright DATE 3/18/82

PART 2 OPERATING ENGINEER'S COMMENTS

The line will be repaired and retested following Rx
reloading when the Rx cavity is drained. All leakage is contained within the drywell floor
drain system.☐ EVENT OF PUBLIC INTEREST☐ TECH. SPEC. VIOLATION☐ NON REPORTABLE OCCURRENCE☐ 14 DAY REPORTABLE/T.5☒ 30 DAY REPORTABLE/T.5,6.6.B.2.d☐ ANNUAL/SPECL REPORT REQ'D☒ 24-HOUR NRC NOTIFICATION REQ'D

TELEPH M. Jordan 3-17-82 1710

REGION III

DATE TIME

TELEGM/TELECOPY J. Keppler 3-18-82 1114

REGION III

DATE TIME

☐ CECO CORPORATE NOTIFICATION MADE
IF ABOVE NOTIFICATION IS PER 10CFR21☐ 5-DAY WRITTEN REPORT REQ'D PER 10CFR21

F. A. Palmer

TELEPH 4-1-82 1319

CECO CORPORATE OFFICER

DATE TIME

A.I.R. #
L.E.R. # 82-14/031-0

Reclassified from a 14 day to a 30 day occurrence.

PRELIMINARY REPORT
COMPLETED AND REVIEWEDMichael Wright
OPERATING ENGINEER

3-18-82

DATE

INVESTIGATED REPORT & RESOLUTION
ACCEPTED BY STATION REVIEWJ. Brunner
3/30/82Michael Wright
3-31-82RESOLUTION APPROVED AND
AUTHORIZED FOR DISTRIBUTION

STATION SUPERINTENDENT

DATE