

## LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99
		O H D B S 1													0 0 - 0 0 0 0 0 0 - 0 0													4 1 1 1 1																																																																							
		LICENSEE CODE													LICENSE NUMBER													LICENSE TYPE													CAT 58																																																										

REPORT SOURCE L 6 0 5 0 0 0 3 4 6 7 0 2 0 9 8 2 8 0 3 2 2 8 2 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 (NP-33-82-11) On 2/9/82 and again on 2/17/82, door 107 was found blocked open. This

0 3 is the access door from the #2 Emergency Core Cooling System Pump Room 115 to the

0 4 Miscellaneous Waste Monitor Tank Room 114. It is part of the negative pressure boun-

0 5 dary for the Emergency Ventilation System (EVS) and when open would reduce the effec-

0 6 tiveness of the system. This was an entry into the action statement of Technical Spe-

0 7 cification 3.6.5.3 which requires this door be closed in Modes 1, 2, 3, and 4. There

0 8 was no danger. The door could have been closed had the door been needed.

8 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE	
0	9	S	H	B	A	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z		
7	8	9	10	11	12	13	13	13	13	13	13	13	13	13	13		
LER RD REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17	8	2	—	0	0	9	—	0	3	L	—	1					
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		EFFECT ON PLANT		SHUTDOW METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
X	H	Z	Z	Z	0	0	0	Y	N	Z	Z	9	9	9	9		
18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause in the first incident is a design deficiency. There is no demineralized  
1 1 water source in Room 114. The cause of the second finding is personnel error in  
1 2 blocking a door without Shift Supervisor permission. FCR 78-309, when implemented,  
1 3 would eliminate the need for flushing. There are ongoing efforts in general orienta-  
1 4 tion and requalification classes as well as special classes with the contractors.

8 9  
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 E (28) 0 6 8 (29) NA B (31) Plant Tour

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA NA

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	37	Z	38	NA		

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	0	0	0
2	0	0	0
3	0	0	0
4	0	0	0
5	0	0	0
6	0	0	0
7	0	0	0
8	0	0	0
9	0	0	0
10	0	0	0
11	0	0	0
12	0	0	0
13	0	0	0
14	0	0	0
15	0	0	0
16	0	0	0
17	0	0	0
18	0	0	0
19	0	0	0
20	0	0	0
21	0	0	0
22	0	0	0
23	0	0	0
24	0	0	0
25	0	0	0
26	0	0	0
27	0	0	0
28	0	0	0
29	0	0	0
30	0	0	0
31	0	0	0
32	0	0	0
33	0	0	0
34	0	0	0
35	0	0	0
36	0	0	0
37	0	0	0
38	0	0	0
39	0	0	0
40	0	0	0
41	0	0	0
42	0	0	0
43	0	0	0
44	0	0	0
45	0	0	0
46	0	0	0
47	0	0	0
48	0	0	0
49	0	0	0
50	0	0	0
51	0	0	0
52	0	0	0
53	0	0	0
54	0	0	0
55	0	0	0
56	0	0	0
57	0	0	0
58	0	0	0
59	0	0	0
60	0	0	0
61	0	0	0
62	0	0	0
63	0	0	0
64	0	0	0
65	0	0	0
66	0	0	0
67	0	0	0
68	0	0	0
69	0	0	0
70	0	0	0
71	0	0	0
72	0	0	0
73	0	0	0
74	0	0	0
75	0	0	0
76	0	0	0
77	0	0	0
78	0	0	0
79	0	0	0
80	0	0	0

8204120372 820322  
PDR ADOCK 05000346  
S PDR

NRC USE ONLY

820412037E 82032E  
 PDR ADDCK 05000346  
 PDR  
 2 0  
 1 S  
 68 69 80