

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | Y | N | M | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
 7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
 0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | 7 | 0 | 3 | 2 | 3 | 8 | 2 | 8 | 94 | 0 | 5 | 8 | 2 | 9  
 7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
 0 2 | During cold shutdown, while conducting routine reactor vessel hydrostatic testing prior  
 0 3 | to startup, water was observed leaking from the insulation on #11 recirculation piping  
 0 4 | discharge to reactor vessel and #15 recirculation piping suction from reactor vessel.  
 0 5 | After removing the insulation and visually examining the #11 discharge safe-end, three  
 0 6 | (3) areas were noted to be "weeping" water. The three leaks are located one each at  
 0 7 | approximately "12 o'clock", "9 o'clock" and "11 o'clock" (all locations were taken  
 0 8 | looking at the reactor vessel). Upon examining the #15 suction safe-end area, one (1) | SEE ATTACHED

0 9 | C | A | 11 | E | 12 | C | 13 | P | I | P | E | X | X | 14 | E | 15 | Z | 16  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20  
 17 | LER NO REPORT NUMBER | 8 | 2 | 21 | 22 | 0 | 0 | 9 | 24 | 25 | 0 | 1 | 28 | 29 | T | 30 | 31 | 0 | 32  
 18 | X | 18 | A | 19 | C | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | Y | 23 | Y | 24 | N | 25 | B | 0 | 6 | 2 | 26  
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
 1 0 | The cause of this occurrence is still being investigated. The site is presently im-  
 1 1 | plementing plans to replace all 10 vessel nozzle to recirculation piping safe-ends.  
 1 2 | \_\_\_\_\_  
 1 3 | \_\_\_\_\_  
 1 4 | \_\_\_\_\_

1 5 | G | 28 | 0 | 0 | 0 | 29 | NA | 30 | C | 31 | Visual Inspection | 32  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
 1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
 1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
 1 8 | 0 | 0 | 0 | 40 | NA | 41  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
 1 9 | Z | 42 | NA | 43  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ISSUED DESCRIPTION (45) PUBLICITY (45) NRC USE ONLY  
 8204140405 820405 Reported to media 3/23/82 - 1800, 3/24/82 - 1800  
 PDR ADOCK 05000220 PDR  
 Kevin McLaughlin PHONE: (315)343-2110  
 68 69 80

LER 82-09

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (Cont'd.)

area was noted to be "weeping" water. This leak is located at approximately "8 o'clock".