## LICENSEE EVENT REPORT

EXHIBIT A

	CONTROL BLOCK: [ ] [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	S   C   N   E   E   3   2   G   O   -   O   O   O   O   O   O   O   O
	REPORT L 6 0 15 10 10 10 2 8 7 7 0 2 2 6 8 2 8 0 4 10 9 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  Non-destructive testing of the HPI hozzle areas revealed that the 3A2 thermal
0131	sleeve was displaced and that there were cracks in the ID of the piping and safe, end. The 3B1 radiographs indicated a partial radial gap between the thermal
0 6	sleeve and safe end. This piping is expected to leak before breaking. A rupture in this line would be classified as a small break LOCA, an accident for which
07	FSAR analysis shows that the plant could be safely shut down. Thus, the health
018	and safety of the public were not affected.
,ola	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
A	THE PORT WELL THE PROPERTY OF THE PORT OF
	The apparent cause of the cracking in the 3A2 safe end and piping appears to be
TIT	thermal fatigue resulting from a loose thermal sleeve. The 3A2 cracked piping,
112	eafe end, and thermal sleeve were replaced. The 3B1 thermal sleeve was hard roll
111	expanded to return the thermal sleeve to its intended condition.
114	
ŢIS į	G 3 C O O O O O O O O O O O O O O O O O O
7 8 9	LEASED OF RELEASE NAMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
17	NUMBER OF TYPE DESCRIPTION 39  0   4   2   (37) E   (38)   Maintenance = 26.44 REM
18	O TO TO TO TO NA
19	COSS OF OR DANAGE TO FACILITY (4)  Z (2)  NA  NA
[2]0	NA NAC USE ONLY
82042	NAME OF PREPARER J. F. Kutzer