NRC FORM 366 NUCLEAR REGULATORY COMMISSION (7.77) LICENSEE EVENT REPORT UPDATE REPORT: Previous Report Date: 11-6-81 CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 4-16-82 (1)0 0 0 0 0 0 0 -M LICENSE NUMBER CON'T REPORT 01 41 21 31 1 0 0 81 L (6) 0 5 0 0 0 3 17 OL 8) SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) At 0730 during normal operation, #12 Diesel Generator was removed from 0 2 service for corrective maintenance per T.S. 3.8.11. The redundant A.C. 3 power sources were verified. #12 Diesel Generator was repaired, tested 4 and returned to service at 2110. Unit 2 was at 100% power. This is not a repetitive event. 6 CODE COMP CAUSE CAUSE VALVE COMPONENT CODE SUBCODE SUBCODE 16 B REVISION SEQUENTIAL OCCURRENCE REPORT EVENT YEAR REPORT NO CODE TYPE NO LER RO 2 REPORT 7 3 0 | 0 Χ 8 NUMBER COMPONENT NPRD-4 EFFECT ON PLANT TTACHMENT SUBMITTED PRIME COMP METHOD FUTURE (22 HOURS FORMSUS SUPPLIER FIO 0 0 L 0 0 24 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27 Two cylinder injectors and a Water Jacket Relief developed leaks on #12 Diesel Generator. The injectors were replaced. The relief was reinstalled with new '0' ring. During this corrective maintenance, 8 air blower discharge flange bolts were discovered broken. All 14 bolts and their inserts were replaced. 80 14 METHOD OF FACILITY DISCOVERY DESCRIPTION (32 OTHER STATUS % POWER Operator Observation 0 0 NA A (31 80 ACTIVITY CONTENT LOCATION OF RELEASE AMOUNT OF ACTIVITY (35 RELEASED_OF RELEASE (34) NA 8 NA 30 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE J Z 38 NA 0 0 0 30 PERSONNEL INJURIES DESCRIPTION (41 NUMBER 0 0 0 0 0 NA 20 LOSS OF OR DAMAGE TO FACILITY (43) TVRE DESCRIPTION NA (42)13 PUBLICITY 8205040245 NAC USE ONLY DESCRIPTION (45) SSUED_ 1(44) N NA 6.9 44 301-269-4747/4853 J.S. Lagiewski/P.G. Ludwig NAME OF PREPARER PHONE .

LER NO.	81-78/3X, Rev. 2
DOCKET NO.	50-317
LICENSE NO.	DPR-53
EVENT DATE	10-08-81
REPORT DATE	04-23-82
ATTACHMENT	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D.)

No. 8 Cylinder North and #12 Cylinder South injector along with #12 Cylinder Water Jacket Relief developed leaks on #12 Diesel Generator. The injector's leaks were due to deterioration of injector's gaskets. The injectors were replaced with rebuilt spares with new gaskets. The Relief Valve Leak was due to foreign material on seating surfaces. The seating surfaces were cleaned and the Relief valve was reinstalled with new 'O' Ring. During the course of this corretive action, 8 of 14 Air Blower Discharge Flange Bolts were discovered to be sheared. The failure of the bolts were determined to be fatigue by material analysis. The bottom 2 or 3 threads of all the inserts were scored preventing the bolts from tightening properly, in effect bottoming out. New inserts were installed with new Grade 5 Bolts after checking for proper thread engagement. No. 12 Diesel Air Blower Discharge Flange and Header were checked for excessive vibration. None existed. A preventive Maintenance Procedure has been initiated to check blower bolts on a bi-weekly basis for detection of possible bolt failure, P.M. Numbers 1-24-M-2W-l and 2-24-M-2W-l. No. 11 and #21 Diesel Blower Discharge Flange Bolts were torque checked and vibration readings were taken. No discrepancies were noted.