

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 AR AN 02 00 -0 00 00 -0 00 04 11 11 11 04 05

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CON'T

01 L 05 00 03 68 00 40 18 20 04 22 82 09

REPORT SOURCE 60 61 DOCKET NUMBER 65 66 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On 4/1/82 while in Mode 1 operation at 100% full power, Control Element

03 Assembly Calculator (CEAC) No. 2 failed during performance of an excore

04 instrument test on Channel 'D'. Core Protection Calculator (CPC)

05 channels were placed in CEAC No. 2 inop. Logging of CEA positions every

06 4 hours was initiated as required by T.S.3.3.1.1. This occurrence is

07 reportable per T.S.6.9.1.9.b. CEAC No. 1 remained operable.

08

09

SYSTEM CODE 11 E 12 E 13 G 14 I 15 N 16 S 17 T 18 R 19 U

CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 14

EVENT YEAR 82 SEQUENTIAL REPORT NO 009 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO 0

17 LER NO REPORT NUMBER 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN Z Z Z Z 0000 N N N C490

23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The momentary erroneous CEA position indication was apparently caused

11 by a computer scan inconsistency. CEAC No. 2 displayed control rods as

12 being farther inserted than actual as verified by other indications.

13 Appropriate penalties were applied by the CPC's. Position indication

14 had returned to normal within a short time. Performance of computer

15 (cont'd on attachment)

FACILITY STATUS E 10 00 29 NA OTHER STATUS 30 METHOD OF DISCOVERY B 31 OPERATOR OBSERVATION 32

15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT Z 33 Z 34 NA AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES NUMBER 000 TYPE 37 Z 38 NA DESCRIPTION 39

17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL INJURIES NUMBER 000 DESCRIPTION 41 NA

18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 NA DESCRIPTION 43

19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PUBLICITY ISSUED N 44 NA DESCRIPTION 45

20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER Patrick RogersPHONE 501/964-31008205040643 820422
PDR ADOCK 05000368
S PDR

LER NO. 50-368/82-009/03L-0 (cont'd)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (cont'd)

diagnostics failed to reveal any abnormality. The monthly surveillance was performed, and CEAC No. 2 was proved operable. CEAC No. 2 was returned to operable status on all CPC channels.